





**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: YN8075L210514

**Estimate**

<b>Customer</b>		
<b>Name:</b>	Sompo Insurance Singapore Private Limited	<b>Date:</b> 20-05-21
<b>Address:</b>	Motor Claims Department	<b>Vehicle No:</b> YN8075L
	50 Raffles Place #05-01 / 06	<b>Model/Make:</b> Mitsubishi
	Singapore Land Tower	<b>Canter:</b> FEB21CR3SDEB
	Singapore 048623	

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Freezer Box Steel Panel <i>R</i>	\$ 980.00	X
2	Freezer Box Handle Bar <i>115 Bent</i>	\$ 250.00	X
3	Front Windscreen Glass <i>one</i>	\$ 870.40	X
4	Windscreen Glass Rubber <i>new</i>	\$ 506.50	X
5	Wiper Panel Garnish <i>Dis/one</i>	\$ 395.30	X
6	Wiper Arm <i>115 Bent/Damaged</i>	\$ 215.40	X
7	Wiper Blade <i>115</i>	\$ 66.50	X
8	Wiper Motor <i>Damaged</i>	\$ 680.50	X
9	Panel <i>R</i>	\$2,494.90	X
10	Panel 'Fuso' Emblem <i>11</i>	\$ 92.50	X
11	Panel 'Corporate' Advertisement & Artwork <i>11</i>	\$ 150.00	X
12	Grille <i>11</i>	\$ 1,123.40	X
13	Dashboard <i>Del/tw</i>	\$ 945.90	X
14	Dashboard Frame <i>11</i>	\$ 625.40	X
15	Bumper <i>11</i>	\$ 991.80	X
16	Wiper Inner Panel <i>11</i>	\$ 845.11	X
17	Heater Unit Assy <i>one</i>	\$ 2,525.52	X
18	Aircon Blower Assy <i>one</i>	\$ 914.42	X
	To check all wiring & electrical component for proper function	\$ 50.00	-
	Remove & reinstall Windscreen Glass to facilitate repairs & perform water	\$ 120.00	-
	Remove & reinstall dashboard, meter instruments, disconnect wiring & Etc's ...	\$ 280.00	-
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 120.00	-
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc's	\$ 1,200.00	-
	To putty & spray painting & including touch up paint on accident affected	\$ 1,000.00	-
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 100.00	-

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 17,543.55

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

\* Submit to insurance

not authorized

LKH  
20/5/21L/S \$6000  
7 days

M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 7234.63

25%

P- 5425.97

L- 2080.00

7505.97