



Exceptional Journeys

Surveyor	:	STEVE LKK
Claim	:	TP AIG
DOA	:	19.05.2021
Emailed	:	16.07.2021, 5pm
Date survey	:	20.05.2021

VEHICLE NO : GBH 9090 PMODEL : BERLINGO L2 1.6WIP : 16542

Material	:	\$ 8,925.60
Labour	:	\$ 6,473.00
Sub-Total	:	\$ 15,398.60
	:	-
Less Excess	:	\$ -
Total	:	\$ 15,398.60
GST 7%	:	\$ 1,077.90
Grand Total	:	\$ 16,476.50
Finalise By/Date	:	LOI / 16/07/2021

REVERT BACK WITHIN 7 DAYS,  
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 7 WORKING DAYS + 4 Days ( 2 ) Weekends  
+ 0 Days ( 0 ) Public holiday  
TOTAL DAYS REPAIR TOOK = 11

TP claim GBG9090U

Claim GIA / LTA fee \_\_\_\_\_

Claim Loss of  Use /  Rental

Claim Medical Fee / Others \_\_\_\_\_

Third Party Report - \_\_\_\_\_



CYCLE &amp; CARRIAGE

## CYCLE &amp; CARRIAGE FRANCE PTE. LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



## PRO-FORMA INVOICE

Company Reg No. 200609327M  
GST Reg No. MR-8500111-X

Invoice Name & Address			Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte. Ltd.	Cust No/Name	/ PECK SENG CRANE & TRANSPORT PT				
MOTOR CLAIM DEPARTMENT	Reg No/Reg Date	GBH9090P / 22/03/2018				
78 SHENTON WAY #09-16	Date In/Mileage	04/06/2021/ 85214				
AIG BUILDING	Chassis/Package	VF77FBHYMHJ754774				
SINGAPORE 079120	Engine No	10JBHW3019068				
Contact No 6419 1000	Make/Model	CITCV/BERLINGO L2 1.6 BLUEHDI ETG				
	Colour/Trim	ZRM GRIS ALUMINIUM / BK BLACK				
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
FAX00001	Credit	16/07/2021/ 15:22	TLE	260 / AiTing	16542	0
Description of Goods / Services				Qty	Unit Price	Disc%
E PNT88000	REPLACE FRONT DAMAGED PARTS, REPLACE FRONT BUMPER, REPAIR LH FRONT FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 500.00	
E PNT88000	REPLACE REAR DAMAGED PARTS, REPLACE LH TAILGATE, RH TAILGATE, REAR BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 1000.00	
E PNT98000	RESPRAY ON FRONT BUMPER, LH FRONT FENDER, TAILGATE LH, TAILGATE RH, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 1520.00	
E PNT88000	REMOVE & INSTALL TAILGATE LH COMPONENTS TO NEW PANEL				✓ 120.00	
E PNT88000	REMOVE & INSTALL TAILGATE RH COMPONENTS TO NEW PANEL				✓ 120.00	
E PNT88000	REMOVE & REINSTALL REAR FLOOR BOARD, TRIMS, CARPETS, AND ALL OTHER ATTACHMENTS TO FACILITATE REPAIR				? 120.00	
A 54900099	CHECK WIRING & ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM				✓ 50.00	
A 10028901	CONDUCT DIAGNOSTIC CHECK AND CLEAR TROUBLE CODE				✓ 225.00	
E PNT88000	REMOVE & INSTALL TAILGATE LH GLASS				✓ 240.00	
E PNT88000	REMOVE & INSTALL TAILGATE RH GLASS				✓ 240.00	
M SUNDAY	SUPPLY REAR WINDSCREEN GLASS SEALANT				✓ 80.00	
E PNT88000	REMOVE & REINSTALL REVERSE SENSOR AND CONDUCT WATER LEAK TEST				✓ 80.00	
M SUNDAY	APPLY ANTI CORROSION ON AFFECTED AREAS				✓ 40.00	
M SUNDAY					✓ 80.00	

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



CYCLE &amp; CARRIAGE

CYCLE &amp; CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



## PRO-FORMA INVOICE

Company Reg No. 200609327M  
GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte. Ltd.	MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120	Cust No/Name Reg No/Reg Date Date In/Mileage Chassis/Package Engine No Make/Model Colour/Trim	/ PECK SENG CRANE & TRANSPORT PT GBH9090P / 22/03/2018 04/06/2021/ 85214 VF77FBHYMHJ754774 10JBHW3019068 CITCV/BERLINGO L2 1.6 BLUEHDI ETG ZRM GRIS ALUMINIUM / BK BLACK		
Contact No 6419 1000					
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
FAX00001	Credit	16/07/2021/ 15:22	TLE	260 / AiTing	16542 0
Description of Goods / Services			Qty	Unit Price	Disc% Amount
SUPPLY BODY PANEL SEALANT					✓ 40.00
M SUNDAY					✓ 40.00
SUPPLY C&C BADGE					✓ 80.00
M SUNDAY					✓ 100.00
SUNDRIES					1000.00
E PNT88000	REMOVE & REINSTALL FRONT PARKING ASSIST SENSOR TO FACILITATE REPAIR				
S SPECIALISTJOB	SUPPLY & REPLACE BOTH FRONT & REAR LICENSE PLATE WITH FRAME				20
E PNT88000	REPLACE REAR FLOOR PANEL & REAR END PANEL → Supp				760.00
E PNT98000	RESPRAY REAR FLOOR PANEL & REAR END PANEL → Supp				38.00
S SPECIALISTJOB	SUPPLY 6 PAX STICKER & 70 KM/H STICKER → Supp				
X FRONT BUMPER		1.00	✓ 1039.00	20.00	831.20
X GUARD GRILLE SUPERIEUR		1.00	✓ 299.00	20.00	239.20
X BUMPER BRACKET		1.00	✓ 254.00	20.00	203.20
X BADGE		1.00	✓ 258.00	20.00	206.40
X GUARD GRILLE INFERIEUR		1.00	✓ 515.00	20.00	412.00
X GRILLE MOULDING SUPERIEUR		1.00	✓ 168.00	20.00	134.40
X BUMPER MOULDING		1.00	✓ 239.00	20.00	191.20
X HEADLIGHT ASSY LH		1.00	✓ 559.00	20.00	447.20
X REAR BUMPER		1.00	✓ 579.00	20.00	463.20
X REAR BUMPER LH ENS		1.00	✓ 267.00	20.00	213.60
X RECESS DOOR		1.00	✓ 68.00	20.00	54.40
X BRACKET SET		1.00	✓ 138.00	20.00	110.40
X LOW RR PAN FIX		1.00	✓ 111.00	20.00	88.80
X SIDE DOOR LH AR	1188	1.00	✓ 1539.00	20.00	1231.20
X SIDE DOOR RH	1259	1.00	✓ 1259.00	20.00	1007.20
X WEATHERSTRIP		1.00	✓ 199.00	20.00	159.20
X BADGE-CITROEN		1.00	✓ 58.00	20.00	46.40
X BADGE-BERLINGO		1.00	✓ 58.00	20.00	46.40

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



CYCLE &amp; CARRIAGE

## CYCLE &amp; CARRIAGE FRANCE PTE. LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



## PRO-FORMA INVOICE

Company Reg No. 200609327M  
GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd.	Cust No/Name	/ PECK SENG CRANE & TRANSPORT PT	
MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120	Reg No/Reg Date	GBH9090P / 22/03/2018	
Contact No 6419 1000	Date In/Mileage	04/06/2021/ 85214	
	Chassis/Package	VF77FBHYMHJ754774	
	Engine No	10JBHW3019068	
	Make/Model	CITCV/BERLINGO L2 1.6 BLUEHDI ETG	
	Colour/Trim	ZRM GRIS ALUMINIUM / BK BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
FAX00001	Credit	16/07/2021/ 15:22	TLE	260 / AiTing	16542	0

Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X DOOR LOCK RH INF		1.00	?	93.00	20.00
X LOCKING RACK LH INF		1.00	?	76.00	20.00
X TAIL-LIGHT LH		1.00	?	168.00	20.00
X LICEN PLAT LAMP		2.00	✓	29.00	20.00
X BUMPER BRACKET		1.00	?	398.00	20.00
X SENSOR		1.00	✓	244.00	20.00
X SENSOR SUPPORT ENS		1.00	✓	161.00	20.00
X BADGE		1.00	✓	59.00	20.00
X DOOR TRIM RH		1.00	✓	120.00	20.00
X REAR PANEL		1.00	✓	754.00	20.00
X BLIND RIVET 7,5X21		3.00	✓	4.00	20.00
X ESPAGN STRIKER RH INF		1.00	✓	42.00	20.00
X ESPAGN STRIKER LH INF		1.00	✓	42.00	20.00
X EXTENSION		1.00	✓	567.00	20.00
X INNER FRAME		1.00	✓	756.00	20.00
Z TEXT					
TP CLAIM AIG GBG9090U					
DOA : 19.05.21					
SURVEYOR STEVE LKK 20.05.21					
REPAIR 07 DAYS					

395

Supp

Guarantee Your Warranty, Maintain with Cycle &amp; Carriage!

Parts	8,925.60		Nett	15,398.60
Labour	6,055.00	7% GST on	15398.60	1077.90
Standard Menu	0.00			
Specialist Job	138.00		Total Payable	16,476.50
Diagnostics Job	0.00		Paid	0.00
Sundry/Others	280.00		Total Due	16,476.50
Total(w/o GST)	15,398.60			

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



## Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: GBH 9090 P

	<u>Parts</u>	<u>Cost (\$)</u>
1	Sensor <u>BR</u>	BR 244.00 ✓✓✓
2	Sensor support ens <u>NEC</u>	NEC 161.00 ✓✓✓
3	Badge <u>NEC</u>	NEC 59.00 ✓✓✓
4	Door trim RH <u>CRU</u>	CRU 120.00 ✓✓✓
5	Rear panel <u>DD</u>	DD 754.00 ✓✓✓
6	Blind rivet 7,5X21 (x3) <u>NEC</u>	NEC 12.00 ✓✓✓
7	Espagn Striker RH Inf <u>BR</u>	BR 42.00 ✓✓✓
8	Espagn Striker LH Inf <u>BR</u>	BR 42.00 ✓✓✓
9	Extension <u>DD</u>	DD 567.00 ✓✓✓
10	Inner Frame <u>DD</u>	DD 756.00 ✓✓✓

Total Labour	2,757.00
Less Discount 20%	551.40
Total after discount	2,205.60

	<u>Labour</u>	<u>Cost (\$)</u>
1	Replace rear floor panel & rear end panel	✓ 1,000.00 ✓✓✓
2	Respray rear floor panel & rear end panel	✓ 760.00 ✓✓✓
3	Supply 6 pax sticker & 70 KM/H sticker	✓ 38.00 ✓✓✓

Total Labour	1,798.00
Taxable amount	4,003.60
7% GST	280.25
<b>Grand total</b>	<b>\$ 4,283.85</b>

Thank You.  
Yours faithfully

LOI AI TING  
SENIOR OFFICER - ADMIN  
CITROEN SERVICE CENTRE  
DID : 6568 4556 / 6568 4501  
FAX : 6567 5258 / 6565 1240

CAR NO: GBH 9090P

WIP: 16542

(ADDITIONAL PARTS CHANGE)

SINO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	④ BUMPER BRACKET	✓ ? / SUPP	✓ RR	98108 450 80	
2	⑮ RADATOR GRILLE MOULDING	✓ ? / SUPP	✓ RR (S10)	16 135 734 80	
3	① TAIL -L   CHIT LH LEFT	✓ ? / SUPP	✓ CUT	96 772 055 80	
4	⑤ REAR BUMPER RIGHT RH	✓ ? / SUPP	✓	7410 FT	
5	⑥ BUMPER BRACKET SET	✓ ? / SUPP	✓ RR (RH)	7416 J1	
6	⑦ BUMPER BRACKET	✓ ? / SUPP	(Temp)	- 01	7414 ZF
7	⑧ OBSTACLE DETECTION SENSOR	✓ ? / SUPP	✓ RR	16 117 355 80	
8	⑨ DETECTION SENSOR SUPPORT	✓ ? / SUPP	✓ RR	7414 ZK	
9	⑩ SIDE FENDER LOGO	✓ ? / SUPP	✓ RR	8666 88	
10	⑪ DOOR LOCK RIGHT	✓ ? / SUPP	✓ RR	8719 EU	
11	⑫ DOOR LOCKING RACK	✓ ? / SUPP	✓ RR	8726 X6	
12	⑬ BADGE (Logo)	✓ ? / SUPP	✓ RR	96 781 130 80	
13	⑭ HD -NERO MISTRAL RH	✓ ? / SUPP	✓ RR	98107 445 2D	
14	⑮ REAR PANEL	✓ ? / SUPP	✓ RR	7243 AQ	
15	⑯ BLIND RIVET (x3)	✓ ? / SUPP	✓ RR	6973 C9	
16	REPAIR RR FLR PNL	✓ ? / SUPP	✓ JTD	✓	
17	REKEY RR END PNL	✓ ? / SUPP	✓		
18	REPAIR RL END PNL & RR FLR PNL	✓ ? / SUPP	✓	1760	
19	add 2 rpm J1 - Total 9 dgs	✓ ? / SUPP			
20		✓ ? / SUPP			

DATE	TAKEN BY
	PHOTO BEFORE PAINT
	PHOTO AFTER PAINT
	PHOTO OF MOUNT TO CELLETE BENCH
	REMOVE AND INSTALL ENGINE
	REMOVE AND INSTALL DASHBAORD
	REMOVE & INSTALL FUEL TANK
	PHOTO UNDERCARRIAGE PARTS

MODEL: BERLINGO

SURVEYOR: STEVE

CAR NO: \_\_\_\_\_

WIP: \_\_\_\_\_ (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	③ HINGED DOOR ESPAGN STRIKER RH	? / SUPP	/ 01	9164 86	9164 86
2	③ HINGED DOOR ESPAGN STRIKER L/H	? / SUPP	/ 01	9164 84	9164 84
3	② EXTEN sION	? / SUPP	/ 01	7239 NV	7239 NV } 8/6/01
4	② REAR PANEL LINER FRAME	? / SUPP			7243 CH
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY
	PHOTO BEFORE PAINT
	PHOTO AFTER PAINT
	PHOTO OF MOUNT TO CELLETE BENCH
	REMOVE AND INSTALL ENGINE
	REMOVE AND INSTALL FUEL TANK
	PHOTO UNDERCARRIAGE PARTS

MODEL: \_\_\_\_\_

SURVEYOR: \_\_\_\_\_



Read & Clear DTC - After

Global test

Expert/Global test


Vehicle\menu\_tgref.s : 81\_02

FAMILY NO.	CONTROL UNIT
	<b>Built-in systems interface</b> BSI
	<b>Engine management ECU</b> EDC17C60
	<b>Anti-lock Braking System (ABS) or Electronic Stability Program (ESP)</b> ESP90
	<b>Automatic or piloted manual gearbox</b>  ★ <b>ECU not recognised</b> <i>Down-grade mode: this information is not guaranteed</i>
	<b>Power steering</b>  ★ <b>ECU not recognised</b> <i>Down-grade mode: this information is not guaranteed</i>
	<b>Diesel additive pump</b> PADDGO_TI_E6
	<b>Battery charge status control unit</b> BECB_GEN2
	<b>Engine wiring housing</b> BSM
	<b>Bodywork conversion unit</b>  ★ <b>BTC</b> <i>Important, ECU present on the vehicle but configured absent</i>
	<b>Trailer relay unit</b>  ★ <b>BSR</b> <i>Important, ECU present on the vehicle but configured absent</i>
	<b>Airbags and pretensioners ECU</b> SAC_AUTOLIV
	<b>Multifunction screen</b> EMF_A




Instrument panel

COMBINE



Parking assistance

AAS




Controls under the steering wheel HDC



Radio

AUTORADIO



**Voltage maintaining device**

\* DMTC

*Important, ECU present on the vehicle  
but configured absent*




**UNDER-INFLATION DETECTION**

*Not present*




**Air conditioning**

*Not present*




**Hands-free Kit / Portable Unit**

*Not present*




**Telematic unit (RTx) or audio-navigation**

*Not present*




**CD changer / External CD player**

*Not present*



**Anti-theft alarm**

*Not present*




**Traction control mode selector**

*Not present*




**Service module / Independent telematic unit**

*Not present*




**Rain and brightness sensor**

*Not present*



**High frequency receiver**

*Not present*



**Vehicle Distance Assistance**

*Not present*