

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

19-May-21

ESTIMATE REPAIR BILL FOR NISSAN SYLPHY REGN NO: SMJ 8454 P

1 pc	Front bumper	\$	620.00 <i>dev</i>
1 pc	Front bumper o/s side bracket	\$	35.00 <i>?</i>
1 pc	Front o/s headlamp	\$	950.00 <i>cut</i>
1 pc	Front o/s fender	\$	740.00 <i>bt</i>
		\$	2,345.00
		Less 35%	\$ 820.75
			\$ 1,524.25

S/NETT

1 set	Front bumper clips	\$	48.00 <i>30.</i>
	Sundry	\$	50.00 <i>x</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 <i>x</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the support panel etc	\$	800.00 <i>300</i>
	To putty and spray painting on Front bumper, front o/s fender, support panel	\$	750.00 <i>400</i>
	To apply rustproofing on the repaired and replaced panels.	\$	100.00 <i>30</i>
		\$	3,452.25

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Taufik 97495749
WP' 2015/21E 315pm
4/5 Posing after repair
taufik@lkhands.com
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date