## PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

19-May-21

## ESTIMATE REPAIR BILL FOR NISSAN SYLPHY REGN NO: SMJ 8454 P

1 pc 1 pc 1 pc 1 pc	Front bumper Front bumper o/s side bracket Front o/s headlamp Front o/s fender	2360 Less 35%	\$\$\$\$\$\$\$	620.00 de 1 35.00 Km 950.00 cub 740.00 bf 2,345.00 820.75 1,524.25
S/NETT	<u>-</u>		\$	J.S. 4800
1 set	Front bumper clips		Ψ	30.00
	Sundry		\$	50.00 × mg
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 × am
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the support panel etc		\$	₹.00 800.00
	To putty and spray painting on Front bumper, front o/s fender, support panel		\$	400 750.00
	To apply rustproofing on the repaired and replaced panels.		\$	3,452.25 760,
	( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )	22	611	
	THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.	1/53	1800	3, Soleys

Tayloth 97495749

WP W/ 20/5/718 315pm

2/5 Perny afor expar

faught & /hhandown

3 days.

## LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subjest to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Paler