

- C00001

SERVICE ESTIMATE

SL: SERVICE SALES - PC
Mr Richard Ting Say Chong
Blk 1 Queen's Road
#11-185

GST Reg.No:M28920628X

Singapore 260001

Inv.No. . . : B&P 0 Page 1
Inv.date. . : 19/05/2021
WIP No. . . : 25230
Veh.In/Out:
*Tel.No. . . : Mobile: 98782005
Reg.No. . . : SMQ4176G
Reg.date . . : 14/11/2019
Mileage . . . : 0
Chassis No: VF1RFA00963211960

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Richard Ting Say

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE TAILGATE, REAR BUMP BUMPER SPOILER, SPOILER MOULDING, REINFORCEMENT, TAILGATE HANDLE, BRACKETS, EMBLEMS, ETC.	0	2200.00	0		2,200.00 S	1100
800	TO PUTTY AND SPRAY PAINT ON TAILGATE, REAR BUMPER, ETC. (PEARL WHITE)	0	1950.00	0		1,950.00 S	1300
802	TO REPLACE REAR WINDSCREEN	0	850.00	0		850.00 S	X
280	TO INSTALL REAR WINDSCREEN	0	280.00	0		280.00 S	X
802	TO TRANSFER TAILGATE MECHANISM	0	250.00	0		250.00 S	/
280	TO CHECK WIRING INCLUDE	0	450.00	0		450.00 S	/
	RESETTING OF ALL ELECTRICAL MODULES						
	BUMPER REAR GS4 BOSS	1.0 EA	928.50			928.50 S	835.65
	TOWING COVER REAR BU	1.0 EA	83.00			83.00 S	
	BUMPER REAR PAD GS4	1.0 EA	483.20			483.20 S	434.88

Steve CLKK) ML AL
16/6/21, 2.00pm P/P

83228813

Steve chen@lkkauto.com

By BL by
6# dyi

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Mr Richard Ting Say Chong
Blk 1 Queen's Road
#11-185

Singapore 260001

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Richard Ting Say

GST Reg.No:M28920628X
0 Page 2
Inv.No. . . : B&P
Inv.date. . : 19/05/2021
WIP No. . . : 25230
Veh.In/Out:
*Tel.No. . . : Mobile: 98782005
Reg.No. . . : SMQ4176G
Reg.date. . : 14/11/2019
Mileage . . : 0
Chassis No: VF1RFA00963211960

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	BUMPER MOUCLING CLIP		10.0 EA	3.70			37.00 S	33.30
	BUMPER REAR LOWER MO		1.0 EA	555.30			555.30 S	499.77
	BUMPER REAR BRACKET		1.0 EA	268.70			268.70 S	
	BUMPER REAR BRACKET		1.0 EA	267.10			267.10 S	
	BUMPER REAR CENTER B		1.0 EA	333.00			333.00 S	
	BUMPER REAR LH SUPPO		1.0 EA	106.00			106.00 S	
	BUMPER REAR RH SUPPO		1.0 EA	106.00			106.00 S	
	BUMPER REAR BRACKET		1.0 EA	157.30			157.30 S	
	BUMPER REAR BRACKET		1.0 EA	136.70			136.70 S	
	BUMPER PAD SUPPORT B		1.0 EA	81.20			81.20 S	
	BUMPER RR CENTER UND		1.0 EA	411.50			411.50 S	
	BUMPER RR RH UNDER C		1.0 EA	279.10			279.10 S	
	BUMPER RR LH UNDER C		1.0 EA	218.80			218.80 S	
	BUMPER REAR REINFORC		1.0 EA	639.20			639.20 S	
	TAILGATE ASSY GS4		1.0 EA	2082.50			2,082.50 S	
	TAILGATE OUTER PANEL		1.0 EA	625.70			625.70 S	563.13
	TAILGATE OUTER PANEL		1.0 EA	392.00			392.00 S	352.80

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Mr Richard Ting Say Chong
Blk 1 Queen's Road
#11-185

Singapore 260001

GST Reg.No: M28920628X

Inv.No. . . : B&P
Inv.date. . : 19/05/2021
WIP No. . . : 25230

0 Page 3

Veh.In/Out:
*Tel.No. . . : Mobile: 98782005
Reg.No. . . : SMQ4176G
Reg.date. . : 14/11/2019
Mileage . . : 0
Chassis No: VF1RFA00963211960

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Richard Ting Say

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	RIVET FIX P / <i>acc</i>	6.0 EA	8.40			50.40 S	45.36
	LOGO REAR "DIAMOND" / <i>acc</i>	1.0 EA	154.30			154.30 S	138.87
	EMBLEM "SCENIC" GS4 / <i>acc</i>	1.0 EA	128.20			128.20 S	115.38
	EMBLEM "RENAULT" REA / <i>acc</i>	1.0 EA	101.10			101.10 S	90.99
	WINDSCREEN REAR GS4 ? <i>X NM</i>	1.0 EA	792.00			792.00 S	
	PRIMER ? <i>X NM</i>	1.0 EA	185.60			185.60 S	
	WINDSCREEN SEALANT ? <i>X NM</i>	2.0 EA	125.50			251.00 S	
	LAMP-FOG, REAR RH GS ? <i>X NM</i>	1.0 EA	238.50			238.50 S	
	LAMP FOG, REAR LH S4 <i>X NM</i>	1.0 EA	346.00			346.00 S	
	TAILLAMP LH GS4 <i>X NM</i>	1.0 EA	452.10			452.10 S	
	TAILLAMP RH GS4 / <i>CUT</i>	1.0 EA	466.20			466.20 S	419.58
	PARKING SENSOR FRT/B ? <i>X NM</i>	4.0 EA	243.00			972.00 S	
	BODY PANEL SEALANT X <i>X NM</i>	1.0 EA	955.20			955.20 S	
	ADHESIVE SEALER FL2 / <i>acc</i>	1.0 EA	709.60			709.60 S	638.64

Gross Total. 19,974.00

Labour Total 5,980.00
Parts Total 13,994.00
Package Total 0.00

Net..... 19,974.00
GST @ 7.0% 1,398.18
Total..... 21,372.20
Paid..... 0.00
Please Pay.. 21,372.20

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Supplementary List

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC
 Mr Richard Ting Say Chong
 Blk 1 Queen's Road
 #11-185

 Singapore 260001

GST Reg.No:M28920628X
 0 Page 1
 Inv.No. . . : B&P
 Inv.date. . : 18/06/2021
 WIP No. . . : 25230
 Veh.In/Out: 16/06/2021
 *Tel.No. . . : Mobile: 98782005
 Reg.No. . . : SMQ4176G
 Reg.date . . : 14/11/2019
 Mileage ... : 18,390
 Chassis No: VF1RFA00963211960

Closed by : Michelle Ong Siew Be
 Svc Consultant : ACC
 Remarks : Mr Richard Ting Say

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR WINDSCREEN	0		850.00	0		850.00 S	550
0080	TO INSTALL REAR WINDSCREEN	0		280.00	0		280.00 S	✓
SOLAR FILM								
802	TO REPAIR END PANEL	0		850.00	0		850.00 S	550
800	TO PUTTY AND SPRAY PAINT ON	0		750.00	0		750.00 S	650
END PANEL								
	TAILGATE ASSY GS4 / <i>BR</i>	1.0	EA	2082.50			2,082.50 S	1874.25
	LAMP-FOG, REAR RH GS / <i>BR</i>	1.0	EA	238.50			238.50 S	214.65
	TAILGATE LAMP-RH GS4 / <i>BR</i>	1.0	EA	466.20			466.20 S	419.58
	BUMPER REAR RH SUPPO / <i>BR</i>	1.0	EA	106.00			106.00 S	95.4
	WINDSCREEN REAR GS4 / <i>nec</i>	1.0	EA	792.00			792.00 S	712.80
	WINDSCREEN SEALANT / <i>nec</i>	2.0	EA	125.50			251.00 S	225.90
	PRIMER / <i>nec</i>	1.0	EA	185.60			185.60 S	167.04

Gross Total. 6,851.80

Labour Total 2,730.00
Parts Total 4,121.80
Package Total 0.00

Net..... 6,851.80
 GST @ 7.0% 479.63
 Total..... 7,331.45
 Paid..... 0.00
 Please Pay.. 7,331.45

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Steve (LKK)
 18/6/21