

### SERVICE ESTIMATE

0 - N00001      SL: NTUC INCOME INSURANCE CO-OPERATIVE NTUC INCOME INSURANCE CO-OPERATIVE 73 Bras Basah #05-01 NTUC Trade Union House Singapore 189556	GST Reg.No:M28920628X Inv.No. . : B&P                      0 Page 1 Inv.date. : 23/06/2021 WIP No. . : 25230 Veh.In/Out: 16/06/2021 23/06/2021 *Tel.No. . : Reg.No. . : SMQ4176G Reg.date . : 14/11/2019 Mileage .. : 18,390 Chassis No: VF1RFA00963211960
Closed by .... : Michelle Ong Siew Be Svc Consultant : ACC Remarks ..... : Mr Richard Ting Say	

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE TAILGATE, REAR BUMPER SPOILER, SPOILER MOULDING, BRACKETS, EMBLEMS, ETC.	0	1100.00	0		1,100.00	S
800	TO PUTTY AND SPRAY PAINT ON TAILGATE, REAR BUMPER, ETC. (PEARL WHITE)520	0	1300.00	0		1,300.00	S
802	TO TRANSFER TAILGATE MECHANISM	0	250.00	0		250.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00	S
802	TO REPLACE REAR WINDSCREEN	0	550.00	0		550.00	S
0080	TO INSTALL REAR WINDSCREEN SOLAR FILM	0	280.00	0		280.00	S
802	TO REPAIR END PANEL	0	550.00	0		550.00	S
800	TO PUTTY AND SPRAY PAINT ON END PANEL	0	650.00	0		650.00	S
①	BUMPER REAR GS4 BOSS	1.0 EA	928.50	10		835.65	S

### SERVICE ESTIMATE

0 - N00001      SL: NTUC INCOME INSURANCE CO-OPERATIVE NTUC INCOME INSURANCE CO-OPERATIVE 73 Bras Basah #05-01 NTUC Trade Union House Singapore 189556	GST Reg.No:M28920628X Inv.No. . : B&P                      0 Page 2 Inv.date. : 23/06/2021 WIP No. . : 25230 Veh.In/Out: 16/06/2021 23/06/2021 *Tel.No. . : Reg.No. . : SMQ4176G Reg.date. : 14/11/2019 Mileage . : 18,390 Chassis No: VF1RFA00963211960
---	---

Closed by .... : Michelle Ong Siew Be  
 Svc Consultant : ACC  
 Remarks ..... : Mr Richard Ting Say

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
3	BUMPER REAR PAD GS4	1.0 EA	483.20	10		434.88	S
4	BUMPER MOUDLING CLIP	10.0 EA	3.70	10		33.30	S
5	BUMPER REAR LOWER MO	1.0 EA	555.30	10		499.77	S
14	TAILGATE OUTER PANEL	1.0 EA	625.70	10		563.13	S
20	TAILGATE OUTER PANEL	1.0 EA	392.00	10		352.80	S
27	RIVET FIX P	6.0 EA	8.40	10		45.36	S
29	LOGO REAR "DIAMOND"	1.0 EA	154.30	10		138.87	S
32	EMBLEM "SCENIC" GS4	1.0 EA	128.20	10		115.38	S
34	EMBLEM "RENAULT" REA	1.0 EA	101.10	10		90.99	S
31	TAILLAMP RH GS4	1.0 EA	466.20	10		419.58	S
37	ADHESIVE SEALER FL2	1.0 EA	709.60	10		638.64	S
51	TAILGATE ASSY GS4	1.0 EA	2082.50	10		1,874.25	S
52	LAMP-FOG, REAR RH GS	1.0 EA	238.50	10		214.65	S
53	TAILGATE LAMP-RH GS4	1.0 EA	466.20	10		419.58	S
54	BUMPER REAR RH SUPPO	1.0 EA	106.00	10		95.40	S
55	WINDSCREEN REAR GS4	1.0 EA	792.00	10		712.80	S
56	WINDSCREEN SEALANT	2.0 EA	125.50	10		225.90	S

**SERVICE ESTIMATE**

0 - N00001      SL: NTUC INCOME INSURANCE CO-OPERATIVE  
 NTUC INCOME INSURANCE CO-OPERATIVE      GST Reg.No:M28920628X  
 73 Bras Basah      Inv.No. . : B&P      0 Page 3  
 #05-01      Inv.date. : 23/06/2021  
 NTUC Trade Union House      WIP No. . : 25230  
 Singapore 189556      Veh.In/Out: 16/06/2021 23/06/2021  
                                  \*Tel.No. . :  
                                  Reg.No. . : SMQ4176G  
 Closed by .... : Michelle Ong Siew Be      Reg.date. : 14/11/2019  
 Svc Consultant : ACC      Mileage . : 18,390  
 Remarks ..... : Mr Richard Ting Say      Chassis No: VF1RFA00963211960

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	 PRIMER	1.0 EA	185.60	10		167.04	S

		Gross Total.	13,007.97
Labour Total	5,130.00	Net.....	13,007.97
Parts Total	7,877.97	GST @ 7.0%	910.56
Package Total	0.00	Total.....	13,918.53
		Paid.....	0.00
		Please Pay..	13,918.53

GST: S=StdRated; O=OutOfScope; Z=ZeroRated