

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : Budget Direct Insurance
Motor Claims Dept

Date : 20 May 2021

Dear Sirs :

Fax : 67250853

RE : ESTIMATE COST FOR MERCEDES BENZ VITO 114 - GBF5888S ACCIDENT INVOLVING GBF5888S & SJB4960Z ON 15/05/2021

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear tailgate	1pc	\$ 2,207.05
2	Rear tailgate hinge @\$167.61ea.	2pcs	\$ 335.22
3	Rear tailgate lock	1pc	\$ 230.90
4	Rear tailgate inner trim	1pc	\$ 112.86
5	VITO	1pc	\$ 49.59
6	114	1pc	\$ 58.71
7	CDI	1pc	\$ 58.71
8	Emblem	1pc	\$ 45.57
9	Rear rubber	1pc	\$ 202.68
10	Rear end panel	1pc	\$ 293.80
11	Rear end panel top garnish	1pc	To be check
12	Rear bumper	1pc	\$ 1,365.17
13	Rear bumper retainer @\$73.17ea	2pcs	\$ 146.34
14	Rear bumper reinforcement	1pc	\$ 284.50
15	Rear bumper reflector n/s.	1pc	\$ 28.33
16	Rear lamp n/s.	1pc	\$ 761.40
17	Rear lamp lower garnish n/s.	1pc	\$ 150.55
			\$ 6,331.38
Less 10%			
			\$ (633.13)
			\$ 5,698.25

	Sum Carried Forward		\$ 5,698.25
18	Rear sensor	1pc	\$ 20.00
19	70KM.	1pc	\$ 15.00
20	6pax	1pc	\$ 15.00
21	Rear windscreen sealant	2pcs	\$ 40.00

Labour Charge & Misc

To remove, replace, repair, weld rear damaged parts	} }	\$ 1,000.00
To R & R sensor wiring.		\$ 100.00
To R & R light wiring		\$ 60.00
To clear broken glass pieces		\$ 120.00
To R & R Rear windscreen glass		\$ 150.00
To putty & spray painting		\$ 1,000.00
Total		\$ 8,218.25

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.