

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : Budget Direct Insurance
Motor Claims Dept

Date : 20 May 2021

Dear Sirs :

Fax : 67250853

RE : ESTIMATE COST FOR MERCEDES BENZ VITO 114 - GBF5888S ACCIDENT INVOLVING GBF5888S & SJB4960Z ON 15/05/2021

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear tailgate <i>bt</i>	1pc	\$ 2,207.05
2	Rear tailgate hinge @\$167.61ea. <i>X</i>	2pcs	\$ 335.22
3	Rear tailgate lock <i>X</i>	1pc	\$ 230.90
4	Rear tailgate inner trim <i>?</i>	1pc	\$ 112.86
5	VITO <i>ne</i>	1pc	\$ 49.59
6	114 <i>ne</i>	1pc	\$ 58.71
7	CDI <i>ne</i>	1pc	\$ 58.71
8	Emblem <i>ne</i>	1pc	\$ 45.57
9	Rear rubber <i>ne</i>	1pc	\$ 202.68
10	Rear end panel <i>?</i>	1pc	\$ 293.80
11	Rear end panel top garnish <i>?</i>	1pc	To be check
12	Rear bumper <i>ca</i>	1pc	\$ 1,365.17
13	Rear bumper retainer @\$73.17ea	2pcs	\$ 146.34
14	Rear bumper reinforcement <i>?</i>	1pc	\$ 284.50
15	Rear bumper reflector n/s. <i>?</i>	1pc	\$ 28.33
16	Rear lamp n/s. <i>?</i>	1pc	\$ 761.40
17	Rear lamp lower garnish n/s. <i>?</i>	1pc	\$ 150.55
			\$ 6,331.38
		Less 10%	\$ (633.13)
			\$ 5,698.25

Sum Carried Forward		\$	5,698.25
18	Rear sensor ?	1pc \$	20.00
19	70KM. <i>nu /</i>	1pc \$	15.00
20	6pax <i>nu /</i>	1pc \$	15.00
21	Rear windscreen sealant <i>nu /</i>	2pcs \$	40.00

Labour Charge & Misc

To remove, replace, repair, weld rear damaged parts	} }	\$	1,000.00 750
To R & R sensor wiring.		\$	100.00 60
To R & R light wiring		\$	60.00 X
To clear broken glass pieces		\$	120.00 X
To R & R Rear windscreen glass		\$	150.00 120
To putty & spray painting		\$	1,000.00 750
Total		\$	<u>8,218.25</u>

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasm
Hp 900 10068
6 days
L/s
20/05/21 @ 1720
Reins after repair