

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/III21006023/KBS3Q2  
**Date:** 28/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006372
<b>Claimant Vehicle No :</b>	SHC5781K	<b>Insured Vehicle No :</b>	SHD2490P
Date of Loss:	15/05/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002167

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHC5781K</b>	Engine No:	HIDDEN
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Chassis No:	VF1ABL15AUC280907
Reg. Date:	11/12/2014 (Man. Year: 2014)	Odometer:	572275 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Falken 5 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Sailun 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,106.91	2,620.19	9,486.72	78.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,450.00	1,010.00	3,440.00	77.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,556.91</b>	<b>3,630.19</b>	<b>12,926.72</b>	<b>78.07</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,900.00</b>		

(S\$)	16,556.91	2,900.00	13,656.91	82.48
<b>+ GST 7.00/7.00% (S\$)</b>	1,158.98	203.00	955.98	82.48
<b>Nett Amount (S\$)</b>	<b>17,715.89</b>	<b>3,103.00</b>	<b>14,612.89</b>	<b>82.48</b>
<b>+ Loss of Use (3.0 x S\$40.00/day) (S\$)</b>		120.00		
<b>+ Car Rental (3.0 x S\$81.13/day) (S\$)</b>		243.39		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,473.84</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,400.00</b>		

INSPECTION

Date of Assignment: 17/05/2021

Date Inspected: 19/05/2021

Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)

2, Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jul 2021)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC5781K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	*- FL
2	1		*ROCKER PANEL OUTER LH (BENT)	Not Consistent With The Impact	1,184.99 FL	*- FL
3	1		*DOOR PANEL REAR LH	Bent	2,844.66 FL	*2,844.66 FL
4	1		*DOOR SEAL REAR LH	Serviceable	119.80 FL	*- FL
5	1		*DOOR WEATHERSTRIP REAR LH	Serviceable	311.60 FL	*- FL
6	1		*DOOR HINGE LOWER REAR LH	Repair	169.90 FL	*- FL
7	1		*DOOR GUIDE REAR LH	Serviceable	136.40 FL	*- FL
8	1		*DOOR REGULATOR REAR LH	Serviceable	450.60 FL	*- FL
9	1		*DOOR REGULATOR MOTOR REAR LH	Serviceable	758.10 FL	*- FL
10	1		*FENDER PANEL REAR LH	Repair	1,933.20 FL	*- FL
11	1		*WHEELARCH REAR LH	Serviceable	275.40 FL	*- FL
12	1		*BUMPER COVER REAR	Serviceable	561.70 FL	*- FL
13	1		*FRONT DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
14	1		*FRONT DOOR STICKER CLASSIC	Not Necessary	80.00 FS	*- FS
15	1		*REAR DOOR STICKER 6555-3333	Necessary	100.00 FS	*60.00 FS
16	1		*RENAULT TYRE RIM	Serviceable	380.00 FS	*- FS
17	1		*RENAULT TYRE	Serviceable	330.00 FS	*- FS
18	1		*ROCKER PANEL CLIP	Not Necessary	65.00 FS	*- FS
19	1		*SET BUMPER CLIP REAR	Not Necessary	85.00 FS	*- FS
20	1		*WHEELARCH CLIP REAR	Not Necessary	75.00 FS	*- FS
21	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
22	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
23	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>13,266.01</b>	<b>2,904.66</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,159.10	284.47

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)						12,106.91
						2,620.19

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	300.00	60.00
2	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	60.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,400.00	400.00
5	TO RUST -PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	440.00
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,450.00</b>	<b>1,010.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >