

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5781K**AAD2103-007***Not Authored**L/Rep @ 2900h**Recovery After Pairs*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

19 MAY 2021**SHC5781K**

VF1ABL15AUC280907

RENAULT

LATITUDE

15/05/2021

IN

11/12/2014

PART

- 1 DOOR PANEL FRT LH
- 1 ROCKER PANEL OUTER LH
- 1 DOOR PANEL REAR LH
- 1 DOOR SEAL REAR LH
- 1 DOOR WEATHERSTRIP REAR LH
- 1 DOOR HINGE LOWER REAR LH
- 1 DOOR GUIDE REAR LH
- 1 DOOR REGULATOR REAR LH
- 1 DOOR REGULATOR MOTOR REAR LH
- 1 FENDER PANEL REAR LH
- 1 WHEELARCH REAR LH
- 1 BUMPER COVER REAR

LIST

\$	R	2,844.66	X
(B1) \$	N.C	1,184.99	X
\$	B	2,844.66	X
\$	S	119.80	X
\$	S	311.60	X
\$	H	169.90	X
\$	S	136.40	X
\$	B	450.60	X
\$	B	758.10	X
\$	R	1,933.20	X
\$	S	275.40	X
\$	S	561.70	X
TOTAL \$		11,591.01	
10% \$		1,159.10	
\$		10,431.91	

Special Nett

- 1 FRONT DOOR STICKER 'Trans-Cab'
- 1 FRONT DOOR STICKER 'Classic'
- 1 REAR DOOR STICKER '6555-3333'
- 1 RENAULT TYRE RIM
- 1 RENAULT TYRE
- 1 ROCKER PANEL CLIP
- 1SET BUMPER CLIP REAR
- 1 WHEELARCH CLIP REAR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	na	80.00	X
\$	na	80.00	X
\$	na	100.00	X
\$	S	380.00	X
\$	S	330.00	
\$	na	65.00	
\$	na	85.00	
\$	na	75.00	
\$	na	150.00	
\$	na	200.00	
\$	na	130.00	
TOTAL \$		1,675.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5781K**AAD2103-007**

TOTAL PARTS	\$	12,106.91
--------------------	-----------	------------------

LABOUR

To transfer of door fittings, attachment and perform water seepage test.

\$	300.00	601
----	--------	-----

To check steering geometry and computer wheel alignment

\$	NA	220.00	X
----	----	--------	---

To remove and refit interior fittings, trimings, garnish, fittings and others, to enable repair.

\$	380.00	601
----	--------	-----

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	1,400.00	4001
----	----------	------

To rust-proofing and apply undercoat of the affected areas.

\$	240.00	301
----	--------	-----

Putty and spray painting of the affected portion.

\$	1,400.00	4001
----	----------	------

To transfer of tire, rim and on wheel balancing.

\$	NA	170.00	X
----	----	--------	---

To Check Electrical Lighting Concerned.

\$	170.00	201
----	--------	-----

To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.

\$	NA	170.00	X
----	----	--------	---

TOTAL	\$	4,450.00
--------------	-----------	-----------------

Over All Total	\$	16,556.91
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~15 DAYS~~

3 days

LKK Auto Consultants hence notify the Repairer of the following:	
• To resurvey before/after spray painting	
• To display damaged part(s) during resurvey	
• Parts prices are subject to confirmation	
• Third party survey is on a "Without Prejudice" basis	
• No illegal modification(s) is allowed	
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
Acknowledged by Repairer	
Signature:	
Date:	