

SK Automobile Pte. Ltd.  
(Co Reg. No. 201500047H)  
8 Kaki Bukit Ave 4 #08-45/46  
Premier@Kaki Bukit S(415875)  
Tel : 6702 1555 Fax : 6702 1444

|                         |                           |                        |                     |
|-------------------------|---------------------------|------------------------|---------------------|
| TO                      | : CHINA TAIPING           | DATE                   | : 18-May-21         |
| ATTENTION               | : MOTOR CLAIMS DEPARTMENT | JOB TYPE               | : T/P CLAIMS        |
| <b>OWNER PARTICULAR</b> |                           | <b>VEHICLE DETAILS</b> |                     |
| NAME                    | : 2XXXXX732N              | VEHICLE NO.            | : SLF5011L          |
| ADDRESS                 | : Hui Zhen.               | MODEL / MAKE           | : MAZDA 3           |
| TEL. NO.                | :                         | CHASSIS NO.            | : JM6BM42A8G0346705 |
| <b>OWNER INSURANCE</b>  |                           | <b>ACCIDENT DETAIL</b> |                     |
| POLICY NO.              | : 5109855704-01           | DATE                   | : 17-May-21         |
|                         |                           | TIME                   | : 06:40HRS          |

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

| S/N | DESCRIPTION                                                   | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|---------------------------------------------------------------|-----|-----------------|------------------|
| 1   | REAR DOOR LH <i>Distorted</i>                                 | 1   | \$ 1,049.00     | \$ 1,049.00      |
| 2   | REAR DOOR OUTER LOCK HANDLE LH <i>Good</i>                    | 1   | \$ 64.70        | \$ 64.70         |
| 3   | REAR DOOR OUTER LOCK HANDLE COVER LH                          | 1   | \$ 26.00        | \$ 26.00         |
| 4   | REAR DOOR OUTER LOCK HANDLE INNER BRACKET LH <i>Distorted</i> | 1   | \$ 46.00        | \$ 46.00         |
| 5   | REAR DOOR BLACK FRAME STICKER SET LH <i>New</i>               | 1   | \$ 88.00        | \$ 88.00         |
| 6   | REAR DOOR GLASS OUTER CHROME MOLDING LH <i>New</i>            | 1   | \$ 78.00        | \$ 78.00         |
| 7   | REAR DOOR HINGE TOP LH <i>Good</i>                            | 1   | \$ 43.00        | \$ 43.00         |
| 8   | REAR DOOR HINGE BOTTOM LH                                     | 1   | \$ 43.00        | \$ 43.00         |
| 9   | REAR DOOR INNER TRIM BOARD LH <i>Good</i>                     | 1   | \$ 745.00       | \$ 745.00        |
| 10  | REAR DOOR POWER WINDOW REGULATOR LH <i>New</i>                | 1   | \$ 99.00        | \$ 99.00         |
| 11  | REAR DOOR POWER WINDOW MOTOR LH <i>New</i>                    | 1   | \$ 106.00       | \$ 106.00        |
| 12  | REAR DOOR POWER WINDOW CHANNEL LH <i>New</i>                  | 1   | \$ 174.00       | \$ 174.00        |
| 13  | REAR DOOR MECHENISM LOCK LH <i>Jammed</i>                     | 1   | \$ 238.00       | \$ 238.00        |
| 14  | REAR DOOR LOCK STRIKER LH <i>New</i>                          | 1   | \$ 42.00        | \$ 42.00         |
| 15  | REAR DOOR WEATHER STRIP LH <i>New</i>                         | 1   | \$ 126.40       | \$ 126.40        |
| 16  | REAR DOOR RUBBER STOPPER LH <i>New</i>                        | 2   | \$ 10.00        | \$ 20.00         |
| 17  | REAR DOOR PILLAR WEATHER STRIP LH <i>New</i>                  | 1   | \$ 105.00       | \$ 105.00        |
| 18  | REAR FENDER LH <i>Distorted</i>                               | 1   | \$ 1,233.00     | \$ 1,233.00      |
| 19  | REAR FENDER INNER SHIELD LH <i>New</i>                        | 1   | \$ 52.00        | \$ 52.00         |
| 20  | REAR FENDER INNER GARNISH LH <i>New</i>                       | 1   | \$ 153.00       | \$ 153.00        |
| 21  | REAR WINDSCREEN MOLDING SET <i>New</i>                        | 1   | \$ 105.00       | \$ 105.00        |
| 22  | ROCKER SIDE PAMEL OUTER LH <i>Distorted Repair</i>            | 1   | \$ 924.00       | \$ 924.00        |
| 23  | REAR WHEEL HOUSE PANEL LH <i>Repair</i>                       | 1   | \$ 1,548.00     | \$ 1,548.00      |
| 24  | REAR TAILLAMP LH <i>Good</i>                                  | 1   | \$ 543.00       | \$ 543.00        |
| 25  | REAR BUMPER <i>2 Distorted</i>                                | 1   | \$ 1,127.00     | \$ 1,127.00      |
| 26  | REAR BUMPER INNER SIDE SHIELD LH <i>Good</i>                  | 1   | \$ 56.00        | \$ 56.00         |
| 27  | REAR BUMPER SIDE RETAINER LH <i>Good</i>                      | 1   | \$ 38.00        | \$ 38.00         |



QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

| S/N | DESCRIPTION                                       | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|---------------------------------------------------|-----|-----------------|------------------|
| 28  | REAR SUSPENSION SHOCK ABSORBER LH <i>new</i>      | 1   | \$ 322.00       | \$ 322.00        |
| 29  | REAR SUSPENSION UPPER ARM LH <i>new</i>           | 1   | \$ 181.00       | \$ 181.00        |
| 30  | REAR SUSPENSION KNUCKLE ARM LH <i>new</i>         | 1   | \$ 685.00       | \$ 685.00        |
| 31  | REAR SUSPENSION KNUCKLE BEARING LH <i>Damaged</i> | 1   | \$ 434.00       | \$ 434.00        |
| 32  | REAR SUSPENSION LOWER ARM LH <i>new</i>           | 1   | \$ 244.00       | \$ 244.00        |
| 33  | REAR SUSPENSION TRAILING ARM LH <i>new</i>        | 1   | \$ 200.00       | \$ 200.00        |
| 34  | REAR SUSPENSION TORSION ARM LH <i>new</i>         | 1   | \$ 115.60       | \$ 115.60        |
| 35  | REAR SUSPENSION THRUS ARM LH <i>new</i>           | 1   | \$ 90.00        | \$ 90.00         |
| 36  | REAR 16" SPORT RIM LH <i>At</i>                   | 1   | \$ 781.00       | \$ 781.00        |

TOTAL PRICE \$ 11,924.70  
 LESS -20% \$ (2,384.94)  
 SUB TOTAL PRICE \$ 9,539.76

6479.70  
 5183.76

CLAIMS DETAIL : PARTS LIST

| S/N | DESCRIPTION                                          | QTY | UNIT S/NETT | TOTAL S/NETT |
|-----|------------------------------------------------------|-----|-------------|--------------|
| 1   | REAR DOOR INNER TRIM BOARD CLIPS SET LH <i>new</i>   | 1   | \$ 60.00    | \$ 60.00     |
| 2   | REAR FENDER SEALANT LH <i>new</i>                    | 1   | \$ 120.00   | \$ 120.00    |
| 3   | REAR FENDER INNER SHIELD CLIPS SET LH <i>Not Nec</i> | 1   | \$ 60.00    | \$ 60.00     |
| 4   | REAR FENDER INNER GARNISH CLIPS SET LH <i>new</i>    | 1   | \$ 40.00    | \$ 40.00     |
| 5   | REAR WINDSCREEN SEALANT WITH PRIMER SET <i>new</i>   | 1   | \$ 100.00   | \$ 100.00    |
| 6   | ROCKER SIDE PAMEL SEALANT LH <i>new</i>              | 1   | \$ 100.00   | \$ 100.00    |
| 7   | REAR WHEEL HOUSE PANEL SEALANT LH <i>new</i>         | 1   | \$ 60.00    | \$ 60.00     |
| 8   | REAR TAILLAMP CLIPS SET LH <i>new</i>                | 1   | \$ 40.00    | \$ 40.00     |
| 9   | REAR BUMPER CLIPS SET <i>Not Nec</i>                 | 1   | \$ 80.00    | \$ 80.00     |

TOTAL \$ 660.00

200

QUOTATION SUMMARY

PAGE 03

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

|                                                                                                     |             |                |      |
|-----------------------------------------------------------------------------------------------------|-------------|----------------|------|
| TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION                                 | \$ 1,600.00 | <del>900</del> | 1000 |
| TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA                                | \$ 1,200.00 | 800.           |      |
| TO APPLY ANTI-RUST & TUFF KOTE                                                                      | \$ 105.00   | 80.            |      |
| TO PERFORM LIGHTING & WIRING CHECK                                                                  | \$ 80.00    | 30             |      |
| TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR                                     | \$ 250.00   | 80.            |      |
| TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM                                                    | \$ 150.00   | 120            |      |
| TO DISMANTLE & REINSTALL REAR DOOR INNER COMPONENT MECHANISM LH TO FACILITATE REPAIR WITH CHECKING  | \$ 250.00   | 80             |      |
| TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD                    | \$ 280.00   | X              |      |
| TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING                            | \$ 80.00    | 50.            |      |
| TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT LH TO PERFORM FACILITATE REPAIRS              | \$ 280.00   | 60.            |      |
| TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT                 | \$ 100.00   | 80.            |      |
| TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR | \$ 280.00   | 80.            |      |
| TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION                                           | \$ 80.00    | X              |      |

TOTAL

\$ 4,735.00

2360



# QUOTATION SUMMARY

PAGE 04

## ESTIMATE REPORT

|                   |   |    |           |
|-------------------|---|----|-----------|
| TOTAL PARTS COST  | : | \$ | 10,199.76 |
| TOTAL LABOUR COST | : | \$ | 4,735.00  |
| TOTAL REPAIR COST | : | \$ | 14,934.76 |

## APPROVED DETAILS

|                          |   |                         |
|--------------------------|---|-------------------------|
| NO. OF REPAIR DAYS       | : | DAYS                    |
| REPAIR UNDER             | : | PART BY PART OR LUMPSUM |
| DATE / TIME OF SURVEY    | : |                         |
| SURVEYED BY / FROM       | : |                         |
| CONTACT NUMBER           | : |                         |
| EMAIL ADDRESS            | : |                         |
| DATE / TIME OF RE-SURVEY | : |                         |
| EXCESS                   | : |                         |

Adrian L  
L/S 21/05/21.

08 Days.

Total: 7743.76.

L/S: 6.2K. ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: