

SK Automobile Pte. Ltd.
 (Co Reg. No. 201500047H)
 8 Kaki Bukit Ave 4 #08-45/46
 Premier@Kaki Bukit S(415875)
 Tel : 6702 1555 Fax : 6702 1444

TO	: CHINA TAIPING	DATE	: 18-May-21
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR		VEHICLE DETAILS	
NAME	: 2XXXXX732N	VEHICLE NO.	: SLF5011L
ADDRESS	: <i>Hui Zhen.</i>	MODEL / MAKE	: MAZDA 3
TEL. NO.	:	CHASSIS NO.	: JM6BM42A8G0346705
OWNER INSUANCE		ACCIDENT DETAIL	
POLICY NO.	: 5109855704-01	DATE	: 17-May-21
		TIME	: 06:40HRS

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR LH <i>Distorted</i>	1	\$ 1,049.00	\$ 1,049.00
2	REAR DOOR OUTER LOCK HANDLE LH <i>2nd</i>	1	\$ 64.70	\$ 64.70
3	REAR DOOR OUTER LOCK HANDLE COVER LH	1	\$ 26.00	\$ 26.00
4	REAR DOOR OUTER LOCK HANDLE INNER BRACKET LH <i>distorted</i>	1	\$ 46.00	\$ 46.00
5	REAR DOOR BLACK FRAME STICKER SET LH <i>new</i>	1	\$ 88.00	\$ 88.00
6	REAR DOOR GLASS OUTER CHROME MOLDING LH <i>new</i>	1	\$ 78.00	\$ 78.00
7	REAR DOOR HINGE TOP LH <i>2nd</i>	1	\$ 43.00	\$ 43.00
8	REAR DOOR HINGE BOTTOM LH	1	\$ 43.00	\$ 43.00
9	REAR DOOR INNER TRIM BOARD LH <i>cracked</i>	1	\$ 745.00	\$ 745.00
10	REAR DOOR POWER WINDOW REGULATOR LH <i>new</i>	1	\$ 99.00	\$ 99.00
11	REAR DOOR POWER WINDOW MOTOR LH <i>new</i>	1	\$ 106.00	\$ 106.00
12	REAR DOOR POWER WINDOW CHANNEL LH <i>new</i>	1	\$ 174.00	\$ 174.00
13	REAR DOOR MECHENISM LOCK LH <i>damaged</i>	1	\$ 238.00	\$ 238.00
14	REAR DOOR LOCK STRIKER LH <i>new</i>	1	\$ 42.00	\$ 42.00
15	REAR DOOR WEATHER STRIP LH <i>new</i>	1	\$ 126.40	\$ 126.40
16	REAR DOOR RUBBER STOPPER LH <i>new</i>	2	\$ 10.00	\$ 20.00
17	REAR DOOR PILLAR WEATHER STRIP LH <i>new</i>	1	\$ 105.00	\$ 105.00
18	REAR FENDER LH <i>Distorted</i>	1	\$ 1,233.00	\$ 1,233.00
19	REAR FENDER INNER SHIELD LH <i>distorted</i>	1	\$ 52.00	\$ 52.00
20	REAR FENDER INNER GARNISH LH <i>new</i>	1	\$ 153.00	\$ 153.00
21	REAR WINDSCREEN MOLDING SET <i>new</i>	1	\$ 105.00	\$ 105.00
22	ROCKER SIDE PAMEL OUTER LH <i>Distorted Repair</i>	1	\$ 924.00	\$ 924.00
23	REAR WHEEL HOUSE PANEL LH <i>Repair</i>	1	\$ 1,548.00	\$ 1,548.00
24	REAR TAILLAMP LH <i>cd</i>	1	\$ 543.00	\$ 543.00
25	REAR BUMPER <i>2 Distorted</i>	1	\$ 1,127.00	\$ 1,127.00
26	REAR BUMPER INNER SIDE SHIELD LH <i>new</i>	1	\$ 56.00	\$ 56.00
27	REAR BUMPER SIDE RETAINER LH <i>new</i>	1	\$ 38.00	\$ 38.00

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	REAR SUSPENSION SHOCK ABSORBER LH <i>new</i>	1	\$ 322.00	\$ 322.00
29	REAR SUSPENSION UPPER ARM LH <i>3 new</i>	1	\$ 181.00	\$ 181.00
30	REAR SUSPENSION KNUCKLE ARM LH <i>new</i>	1	\$ 685.00	\$ 685.00
31	REAR SUSPENSION KNUCKLE BEARING LH <i>Damaged</i>	1	\$ 434.00	\$ 434.00
32	REAR SUSPENSION LOWER ARM LH <i>new</i>	1	\$ 244.00	\$ 244.00
33	REAR SUSPENSION TRAILING ARM LH <i>new</i>	1	\$ 200.00	\$ 200.00
34	REAR SUSPENSION TORSION ARM LH	1	\$ 115.60	\$ 115.60
35	REAR SUSPENSION THRUS ARM LH <i>new</i>	1	\$ 90.00	\$ 90.00
36	REAR 16" SPORT RIM LH <i>at</i>	1	\$ 781.00	\$ 781.00

6479.70
5183.76

TOTAL PRICE \$ 11,924.70
LESS -20% \$ (2,384.94)
SUB TOTAL PRICE \$ 9,539.76

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR DOOR INNER TRIM BOARD CLIPS SET LH <i>new</i>	1	\$ 60.00	\$ 60.00
2	REAR FENDER SEALANT LH <i>new</i>	1	\$ 120.00	\$ 120.00
3	REAR FENDER INNER SHIELD CLIPS SET LH <i>Not Nec</i>	1	\$ 60.00	\$ 60.00
4	REAR FENDER INNER GARNISH CLIPS SET LH <i>new</i>	1	\$ 40.00	\$ 40.00
5	REAR WINDSCREEN SEALANT WITH PRIMER SET <i>new</i>	1	\$ 100.00	\$ 100.00
6	ROCKER SIDE PAMEL SEALANT LH <i>new</i>	1	\$ 100.00	\$ 100.00
7	REAR WHEEL HOUSE PANEL SEALANT LH <i>new</i>	1	\$ 60.00	\$ 60.00
8	REAR TAILLAMP CLIPS SET LH <i>new</i>	1	\$ 40.00	\$ 40.00
9	REAR BUMPER CLIPS SET <i>Not Nec</i>	1	\$ 80.00	\$ 80.00

TOTAL \$ 660.00

200

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,600.00	900	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,200.00	800.	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 105.00	80.	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR	\$ 250.00	80.	
TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM	\$ 150.00	120	
TO DISMANTLE & REINSTALL REAR DOOR INNER COMPONENT MECHANISM LH TO FACILITATE REPAIR WITH CHECKING	\$ 250.00	80	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 280.00	X	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	50.	
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT LH TO PERFORM FACILITATE REPAIRS	\$ 280.00	60.	
TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	\$ 100.00	80.	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	80.	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	X	

TOTAL

\$ 4,735.00

2360

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	10,199.76
TOTAL LABOUR COST	:	\$	4,735.00
TOTAL REPAIR COST	:	\$	<u>14,934.76</u>

APPROVED DETAILS

NO. OF REPAIR DAYS : DAYS

REPAIR UNDER : PART BY PART OR LUMP SUM

DATE / TIME OF SURVEY :

SURVEYED BY / FROM :

CONTACT NUMBER :

EMAIL ADDRESS :

DATE / TIME OF RE-SURVEY :

EXCESS :

Adrian G
L/S 21/05/21.

08 Days.

Total: 7743.76

L/S: 6.2K. ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: