

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Alfred Toh

Date: 01 Jun 2021

**Preliminary Advice**

Insured Vehicle No	: PC1296B	Accident Date	: 17/05/2021
TP Vehicle No	: SLF5011L	Assignment Date	: 20/05/2021
Make	: MAZDA 3	Est. Duration of Repair	: 8
Date of Inspection	: 21/05/2021		
Inspection At	: SK AUTOMOBILE HUB - KAKI BUKIT (HQ) 23 KAKI BUKIT AVE 4, #03-01 SINGAPORE 415933		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,934.76
Revised Amount	:S\$	7,743.76
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,743.76
Lump Sum Repair	:S\$	6,200.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :