



YEE AUTO PTE LTD

180 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 8457 5788 Fax: 8252 8459 Mobile: 8887 4031
Email: yeeautopte Ltd@gmail.com
Registration No: 201719251W GST No: 201719251W

M/S: AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Own Damage
Accident Date: 19/05/2021

Estimate No: ES2100050
Date: 20 May 2021
Policy No:
Veh Reg No: GBH8888L
Make/Model: NISSAN CABSTAR 3.0
5M/T ABS 2DR 2WD
EURO 5
Chassis No: JN1SC2F24Z0857577
Engine No: ZD30001311N
Reg. Date: 17/09/2015

Estimate Repair Cost to Vehicle No: GBH8888L

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 ERP IU BRACKET	40.00	1 PC	40.00	201n
2 FRONT EMBLEM 'CABSTAR'	62.00	1 PC	62.00	✓
3 FRONT NUMBER PLATE	60.00	1 PC	60.00	201n
4 REAR NUMBER PLATE	60.00	1 PC	60.00	X
			222.00	222.00
Spare Parts				
5 AIR CON CONDENSER PRESSURE PIPE	464.40	1 PC	464.40	✓
6 AIR CON CONDENSER SUCTION PIPE	513.90	1 PC	513.90	✓
7 DIESEL TANK	1,500.85	1 PC	1,500.85	✓
8 DIESEL TANK HOLDER BRACKET	275.15	1 PC	275.15	X
9 FRONT BUMPER	556.30	1 PC	556.30	✓
10 FRONT BUMPER CLIPS	80.00	1 SET	80.00	X
11 FRONT BUMPER REINFORCEMENT	328.10	1 PC	328.10	?
12 FRONT GRILLE	669.50	1 PC	669.50	✓
13 FRONT GRILLE LOGO	65.00	1 PC	65.00	✓
14 FRONT HEAD LAMP - LH	602.50	1 PC	602.50	✓
15 FRONT HEAD LAMP - RH	602.50	1 PC	602.50	✓
16 FRONT HEAD LAMP LOWER GARNISH - LH	268.00	1 PC	268.00	?
17 FRONT HEAD LAMP LOWER GARNISH - RH	268.00	1 PC	268.00	?
18 FRONT PANEL	1,979.50	1 PC	1,979.50	X
19 FRONT SIDE PANEL - LH	118.10	1 PC	118.10	X
20 FRONT SIDE PANEL - RH	118.10	1 PC	118.10	X
21 FRONT WINDSCREEN GLASS	1,178.75	1 PC	1,178.75	✓
22 FRONT WINDSCREEN MOULDING	384.50	1 PC	384.50	✓
23 FRONT WINDSCREEN SEALANT	60.00	1 PC	60.00	✓
24 FRONT WIPER ARM - LH	287.50	1 PC	287.50	X
25 FRONT WIPER ARM COVER - LH	30.00	1 PC	30.00	X
26 FRONT WIPER BLADE - LH	40.00	1 PC	40.00	X
27 FRONT WIPER BLADE - RH	40.00	1 PC	40.00	X
28 FRONT WIPER MOTOR	729.00	1 PC	729.00	X
29 FRONT WIPER NOZZLE - LH	85.00	1 PC	85.00	X
30 FRONT WIPER PANEL COVER	681.20	1 PC	681.20	X
31 WATER COOLANT	50.00	1 PC	50.00	?
32 FRONT BUMPER TOW HOOK	320.25	1 PC	320.25	X
33 FRONT CROSS MEMBER	750.00	1 PC	750.00	?



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte ltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S: AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Own Damage
Accident Date: 19/05/2021

Estimate No: ES2100050
Date: 20 May 2021
Policy No:
Veh Reg No: GBH8888L
Make/Model: NISSAN CABSTAR 3.0
5M/T ABS 2DR 2WD
EURO 5
Chassis No: JN1SC2F24Z0857577
Engine No: ZD30001311N
Reg. Date: 17/09/2015

Estimate Repair Cost to Vehicle No :GBH8888L

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
35 FRONT KNUCKLE ARM - RH	641.70	1 PC	641.70 ?	
36 FRONT LOWER ARM - LH	320.00	1 PC	320.00 ?	
37 FRONT LOWER ARM - RH	320.00	1 PC	320.00 ?	
38 FRONT SHOCK ABSORBER - LH	285.90	1 PC	285.90 ?	
39 FRONT SHOCK ABSORBER - RH	285.90	1 PC	285.90 ?	
40 FRONT STEERING RACK	2,800.00	1 PC	2,800.00 ?	
41 FRONT STEP GARNISH - LH	185.00	1 PC	185.00 ?	
42 FRONT STEP GARNISH - RH	185.00	1 PC	185.00 ?	
43 FRONT STEP INNER PANEL - LH	265.00	1 PC	265.00 X	
44 FRONT STEP INNER PANEL - RH	265.00	1 PC	265.00 X	
45 FRONT UPPER ARM - LH	475.20	1 PC	475.20 ?	
46 FRONT UPPER ARM - RH	475.20	1 PC	475.20 ?	
47 FRONT WHEEL BEARING - LH	375.20	1 PC	375.20 ?	
48 FRONT WHEEL BEARING - RH	375.20	1 PC	375.20 ?	
49 FRONT STEERING BOX (LOWER)	880.15	1 PC	880.15 ?	
			21,822.25	21,822.25
Labour				
50 AIRCON GAS	80.00	1 JOB	80.00 ✓	
51 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,600.00	1 JOB	1,600.00 500	
52 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,200.00	1 JOB	1,200.00 600	
53 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	100.00	1 JOB	100.00 X	
54 TO REMOVE/REFIX FRONTWINDSCREEN TO FACILITATE REPAIRS.	250.00	1 JOB	250.00 120	
55 TO REMOVE/RENEW AIRCON CONDENSER & REBELL GAS	300.00	1 PC	300.00 100	
56 TO REMOVE/REPLACE FRONT UNDERBODY PROTECTANT	400.00	1 PC	400.00 ?	
57 TO TOW VEHICLE TO WORKSHOP.	180.00	1 JOB	180.00 ?	
58 WHEEL ALIGNMENT	180.00	1 T	180.00 60	
59 TO CHECK WIRING FUNCTIONS.	100.00	1 JOB	100.00 20	
			4,390.00	4,390.00
			26,434.25	

108

Law Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: