

ASS. REC. BY:

REF:

AIG/ CS/AIG21006033/Kvf3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 1900156362

Claims No. 6897717322SG

Sum Insured: _____ Excess: 600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 835k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6-8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBH 88882 Yr Regn: 09, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS Cabstar c.c. 2953

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 144552 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNISC 2F-247-20857577

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NIS / S/Rlm / STD A/Rlm or

Tyre Size: F: 0175u 195R15X8

R: Yoko 155R12X80

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal: 7 mm R/Bal: 6 mm

L/Bal: 7 mm L/Bal: 22 mm

D.O.A. 19/5/21 D.O.I. 21/5/2021

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / UIC / Rooftop or

8 UIC

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/12/21 LS \$6000 confirmed by email (Red 21,765.85, 78%)

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 28/12/21-typist

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS, SI

Paras

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format: Merimen

Lump Sum / I.B.T: (\$ 6000)



YEE AUTO PTE LTD

180 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 676722
Tel: 8457 5788 Fax: 8252 8459 Mobile: 8887 4031
Email: yeeautopte ltd@gmail.com
Registration No: 201719251W GST No: 201719251W

M/S: AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

Estimate No: ES2100050
Date: 20 May 2021
Policy No:
Veh Reg No: GBH8888L
Make/Model: NISSAN CABSTAR 3.0
5M/T ABS 2DR 2WD
EURO 5
Chassis No: JN1SC2F24Z0857577
Engine No: ZD30001311N
Reg. Date: 17/09/2015

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Own Damage
Accident Date: 19/05/2021

Not Authorized

6 Days

Primary After Party

Ex ?

6-8 days

Estimate Repair Cost to Vehicle No: GBH8888L

Description	U/Price	Quantity	List Price SS	Amount SS
Net Price				
1 ERP IU BRACKET	40.00	1 PC	40.00	261.00
2 FRONT EMBLEM 'CABSTAR'	62.00	1 PC	62.00	✓
3 FRONT NUMBER PLATE	60.00	1 PC	60.00	201.00
4 REAR NUMBER PLATE	60.00	1 PC	60.00	X
			222.00	222.00
Spare Parts				
5 AIR CON CONDENSER PRESSURE PIPE	464.40	1 PC	464.40	✓
6 AIR CON CONDENSER SUCTION PIPE	513.90	1 PC	513.90	✓
7 DIESEL TANK	1,500.85	1 PC	1,500.85	✓
8 DIESEL TANK HOLDER BRACKET	275.15	1 PC	275.15	✓
9 FRONT BUMPER	556.30	1 PC	556.30	✓
10 FRONT BUMPER CLIPS	80.00	1 SET	80.00	X
11 FRONT BUMPER REINFORCEMENT	328.10	1 PC	328.10	?
12 FRONT GRILLE	669.50	1 PC	669.50	✓
13 FRONT GRILLE LOGO	65.00	1 PC	65.00	✓
14 FRONT HEAD LAMP - LH	602.50	1 PC	602.50	✓
15 FRONT HEAD LAMP - RH	602.50	1 PC	602.50	✓
16 FRONT HEAD LAMP LOWER GARNISH - LH	268.00	1 PC	268.00	?
17 FRONT HEAD LAMP LOWER GARNISH - RH	268.00	1 PC	268.00	?
18 FRONT PANEL	1,979.50	1 PC	1,979.50	X
19 FRONT SIDE PANEL - LH	118.10	1 PC	118.10	X
20 FRONT SIDE PANEL - RH	118.10	1 PC	118.10	X
21 FRONT WINDSCREEN GLASS	1,178.75	1 PC	1,178.75	✓
22 FRONT WINDSCREEN MOULDING	384.50	1 PC	384.50	✓
23 FRONT WINDSCREEN SEALANT	60.00	1 PC	60.00	401.00
24 FRONT WIPER ARM - LH	287.50	1 PC	287.50	X
25 FRONT WIPER ARM COVER - LH	30.00	1 PC	30.00	X
26 FRONT WIPER BLADE - LH	40.00	1 PC	40.00	X
27 FRONT WIPER BLADE - RH	40.00	1 PC	40.00	X
28 FRONT WIPER MOTOR	729.00	1 PC	729.00	X
29 FRONT WIPER NOZZLE - LH	85.00	1 PC	85.00	X
30 FRONT WIPER PANEL COVER	681.20	1 PC	681.20	X
31 WATER COOLANT	50.00	1 PC	50.00	?
32 FRONT BUMPER TOW HOOK	320.25	1 PC	320.25	X
33 FRONT CROSS MEMBER	750.00	1 PC	750.00	?



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S: AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Own Damage
Accident Date: 19/05/2021

Estimate No: ES2100050
Date: 20 May 2021
Policy No:
Veh Reg No: GBH8888L
Make/Model: NISSAN CABSTAR 3.0
5M/T ABS 2DR 2WD
EURO 5
Chassis No: JN1SC2F24Z0857577
Engine No: ZD30001311N
Reg. Date: 17/09/2015

Estimate Repair Cost to Vehicle No :GBH8888L

Description	U/Price	Quantity	List Price	Amount
			SS	SS
35 FRONT KNUCKLE ARM - RH	641.70	1 PC	641.70	?
36 FRONT LOWER ARM - LH	320.00	1 PC	320.00	?
37 FRONT LOWER ARM - RH	320.00	1 PC	320.00	?
38 FRONT SHOCK ABSORBER - LH	285.90	1 PC	285.90	?
39 FRONT SHOCK ABSORBER - RH	285.90	1 PC	285.90	?
40 FRONT STEERING RACK	2,800.00	1 PC	2,800.00	?
41 FRONT STEP GARNISH - LH	185.00	1 PC	185.00	?
42 FRONT STEP GARNISH - RH	185.00	1 PC	185.00	?
43 FRONT STEP INNER PANEL - LH	265.00	1 PC	265.00	X
44 FRONT STEP INNER PANEL - RH	265.00	1 PC	265.00	X
45 FRONT UPPER ARM - LH	475.20	1 PC	475.20	?
46 FRONT UPPER ARM - RH	475.20	1 PC	475.20	?
47 FRONT WHEEL BEARING - LH	375.20	1 PC	375.20	?
48 FRONT WHEEL BEARING - RH	375.20	1 PC	375.20	?
49 FRONT STEERING BOX (LOWER)	880.15	1 PC	880.15	?
			21,822.25	21,822.25
Labour				
50 AIRCON GAS	80.00	1 JOB	80.00	✓
51 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,600.00	1 JOB	1,600.00	500
52 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,200.00	1 JOB	1,200.00	600
53 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	100.00	1 JOB	100.00	X
54 TO REMOVE/REFIX FRONTWINDSCREEN TO FACILITATE REPAIRS.	250.00	1 JOB	250.00	120
55 TO REMOVE/RENEW AIRCON CONDENSER & REBILL GAS	300.00	1 PC	300.00	100
56 TO REMOVE/REPLACE FRONT UNDERBODY PROTECTANT	400.00	1 PC	400.00	?
57 TO TOW VEHICLE TO WORKSHOP.	180.00	1 JOB	180.00	?
58 WHEEL ALIGNMENT	180.00	1 T	180.00	60
59 TO CHECK WIRING FUNCTIONS.	100.00	1 JOB	100.00	20
			4,390.00	4,390.00

REPAIR LABOUR

• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	20/05/2021 13:49 (SGT)
Date of Accident	19/05/2021 10:00 (SGT)
Exact Location of Accident	Defu South Street 1, Singapore
Additional Location Information	Defu South Construction Site
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH8888L
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	Keong Industries Pte Ltd
Company Reg No	2XXXXXX280C
Email Address	vell@keongindustries.com.sg
Mobile Phone No	(Phone) +65-63672722
Alternative Phone No	(Office) +65-63672722

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Cabstar
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	3000

INSURANCE COMPANY


Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900156362-01
Cover Note Number	-

DRIVER

Name of Driver	Chen Jinxing
NRIC No	SXXXX880H

SKETCH PLAN A: GBH 8888L

Defu South Construction Site (Honggang Planning Area)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19/05/2021 @ 1000hr. I was driving ~~long~~ on site at Defu South Construction Site (Honggang Planning Area). When I was doing a three point turn, As I was turning I didn't realise there was a uneven step in front of me and causes my lorry to fall half vehicle into it.

*Kindly send my GFA report to me & my workshop
Yee Auto Pte Ltd yeeautopte1td@gmail.com

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Angie Soh
20 MAY 2021