

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0435/2021/KS
DATE : 20-May-21
WIP : 27094

Veron

\$4891.44 04 days

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/5/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : DR LEE KAH YANN
ADDRESS : 48 WEST COAST ROAD
#04-49
SINGAPORE 126839
TELEPHONE : HP +65 90033488
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 170003842-04
VEHICLE NO : SKN 3088 Z
MODEL CODE : AUDI A3 SPORTBACK 1.0 TFSI
MODEL YEAR : 12/5/2017
ENGINE NO : CHZ 350818
CHASSIS NO : WAUZZZ8V4HA121747
MILEAGE : -
DATE IN :
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-May-21
PLACE OF ACCIDENT : AYE, SINGAPORE (NEAR CLEMENTI EXIT)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SKN 3088 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	S/N S	350.00	280 ✓
2	TO DISMANTLE AND RENEW LHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S	1,050.00	500 ✓
3	TO RESPRAY LHS REAR DOOR, DOOR HANDLE AND LHS REAR FENDER.	S	1,200.00 2,300.00	1200 ✓ 2 X 550 = 1100 Handle = 100.
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N S	192.00	✓ ✓ 1200
TOTAL LABOUR CHARGES		:	<u>\$ 3,892.00</u>	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 3088 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR DOOR LHS <i>Dented</i>	1	\$ 2,767.00	✓ 2213.60
2	REAR DOOR SEAL LH <i>on</i>	1	\$ 161.00	✓ 128.40
3	BONDING AGENT	1	\$ 49.00	? X
4	CLEANIN SOLUTION	1	\$ 68.00	? X
5	APPLICATOR	1	\$ 8.00	? X
6	REAR DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 129.00	+
7	REAR DOOR CATCH LHS <i>Damaged.</i>	1	\$ 94.00	? 74.80
8	REAR DOOR HANDLE, EXTERIOR LH <i>Dented</i>	1	\$ 374.00	✓ 298.80
9	REAR DOOR HANDLE, HOUSING LH <i>new</i>	1	\$ 52.00	+
10	REAR DOOR SLIDE VALVE <i>new</i>	1	\$ 22.00	+
11	UNDERLAY <i>new</i>	1	\$ 6.00	+
12	REAR DOOR MOUNTING BAR <i>new</i>	1	\$ 162.00	+
13	REAR DOOR BOWDEN CABLE LH <i>new</i>	1	\$ 52.00	+
14	SUNDRIES <i>Nec.</i>	1	\$ 200.00	? 3.84
TOTAL SPARE PARTS		:	\$ 4,144.00	
TOTAL LABOUR CHARGES		:	\$ 3,892.00	
GRAND TOTAL		:	\$ 8,036.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Lj
SURVEYED DATE : 20/05/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 04 days S.S.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT