



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 58477
Date Estimated : 20/05/2021
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Wong Shuh Mang
63 West Coast Way
#01-25

Singapore 127021

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMW7997C	WBA4S32030AG24539	27/09/2019	420i COUPE	20942

DESCRIPTION

Replace front bumper include attachment etc

Painting front bumper

To check electrical wiring system at the front section
for proper function including adjustment of headlights.

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct check for
proper function.

To replace right headlight.

Sundries.

VALUE

850 1,275.00

986 1,038.00

168 177.00

168 177.00

456 481.00

80.7 150.00

Total Labour 1: 3,298.00

DESCRIPTION

FRT BUMPER TOP CARRIER ? x n

DEFORMATION ELEMENT FRT RH ? x n

FRT SHOCK ABSORBER ? x n

FRT LH BOTTOM MOUNTING SIDE PANEL x n

FRT RH BOTTOM MOUNTING SIDE PANEL ? x n

FRT LH TOP MOUNTING SIDE PANEL x n

FRT RH TOP MOUNTING SIDE PANEL ? x n

Closed grid, right fog cover m x n

RH TRIM SPORT LINE m y

FINISHER ROD CENTRE (SPORT LINE) ? s c a

FRT BUMPER PANEL PRIMED (LINES) d e

FRT RH GRILLE (SPORT) x n

RH SUPPORT ? x n

RH COVER BOTTOM ? f n

DEFLECTOR LIP RH ? f n

PLAQUE 82MM m

RH HEADLIGHT LED TECHNOLOGY s c a

DECOUPLING RING PDC TORQUE CONVERTE m

QTY

PRIC

VALUE

1 417.60 417.60

1 95.40 95.40

1 54.85 54.85

1 38.15 38.15

1 38.15 38.15

1 26.15 26.15

1 26.15 26.15

1 90.95 90.95

1 123.90 123.90

1 53.35 53.35

1 1,042.20 1,042.20

1 129.25 129.25

1 132.15 132.15

1 117.70 117.70

1 68.35 68.35

1 71.95 71.95

1 2,681.50 2,681.50

4 5.15 20.60

2685.95

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 5

Estimate No. : b1 58477
Date Estimated : 20/05/2021
Prepared By : Chua Kee Sin

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
BMW7997C	WBA4S32030AG24539	27/09/2019	420i COUPE	20942

DESCRIPTION	QTY	PRIC	VALUE
ULTRASONIC SENSOR BLACK <i>nw</i>	<i>1pc</i>	<i>239.25</i>	957.00
Total Parts :			6,185.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time *07/06/2019 @ 1050* Excess S\$ _____

Surveyor's Name *Rafael* Sign _____

Surveyor's Tel *90010060* Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend *4 days*



Labour 1	:	3,298.00
Parts	:	6,185.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	663.83
Grand Total	:	10,147.18

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Estimate No. : **b1 58477**
 Date Estimated : **20/05/2021**
 Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -

Wong Shuh Mang
63 West Coast Way
#01-25

Singapore 127021

- ACCOUNT - 158

Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMW7997C	WBA4S32030AG24E	27/09/2019	420i COUPE	20942

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# RH FOG LAMP SUPPORT cra ✓	42.30	1.00	0.00	42.30
# SET MOUNTING PDC/PMA SENSOR FRT nec ✓	76.10	1.00	0.00	76.10
# (DG/SL) ADHESIVE SET K6 nec ✓	53.05	1.00	0.00	53.05

SUPPLEMENTARY ITEMS

Total Labour :

Total Parts : 171.45