



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI20007035/Evf3e2-1 Date: 07/06/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMK 8542M	Veh. Inspected	SMM 6938H	
Policy No.	DMPCSN30841519000	Coverage (\$)	0.00	
Claim No.	SNM20D202219/C03/CHNGPW	Excess (\$)	0.00	
Assign From	ADELINE CHNG	Assign Date	21/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GP51339177	Colour	GREY	
Odometer	76402 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	WEST LAKE	4 mm	
L/H Front Tyre	185/60 R15	WEST LAKE	4 mm	
R/H Rear Tyre	185/60 R15	WEST LAKE	4 mm	
L/H Rear Tyre	185/60 R15	WEST LAKE	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY, REAR AND FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/06/2020	Inspection Date	07/07/2020	
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		30 Working Days		