

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21006052/UBS3Q2
Date: 20/08/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLH40A	Insured Vehicle No :	SLW8113S
Date of Loss:	19/05/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002165

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH40A	Engine No:	50379662B47D20B
Make & Model:	BMW X5 XDRIVE 30D, 3.0 LED SR HUD NAV 7 SEATER (A)	Chassis No:	WBALS020100U15930
Reg. Date:	04/11/2016 (Man. Year: 2016)	Odometer:	71456 km
Colour:	White/Blue		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/40 R20	Rear Tyre Size:	315/30 R20
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,581.00	450.00	2,131.00	82.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	530.00	730.00	57.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,841.00	980.00	2,861.00	74.49
+ GST 7.00/7.00% (S\$)	268.87	68.60	200.27	74.49

Nett Amount (\$)	4,109.87	1,048.60	3,061.27	74.49
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment:	21/05/2021		
Date Inspected:	29/06/2021	Inspected At:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Singapore 408711
Estimated Period of Repair:	2.0 days		

Adjuster:	MARCUS CHUA	Manager:	CHUA ZHEN LI
------------------	-------------	-----------------	--------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Aug 2021)
Parts:	M1-SUV	BMW X5 XDRIVE 30D 3.0 LED SR HUD NAV 7 SEATER (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH40A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Repair	1,951.00 F	*- F
2	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 F	*- F
3	1		*STICKER WRAP ON FRONT BUMPER	Damaged	580.00 FS	*450.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					2,581.00	450.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CUT ,OUT RENEW KNOCKING & WELDING FRONT BUMPER ,REMOVE & INSTALL ALL DAMAGE PARTS STRAIGHTEN & REALIGN BODY }	New	380.00	280.00
2	DIAGNOSTIC & RESET }	New	300.00	0.00
3	SPRAY PAINTING ON DAMAGE PARTS	New	580.00	250.00
Gross Labour Cost (\$\$)			1,260.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >