

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLH40A/2105046

21th May 2021

The Manager
Motor Claim Department
India International Insurance Pte Ltd
64 Cecil Street
#04/05 IOB Building
Singapore 049711

Date of Accident : 19th May 2021
Location : Blk 543 Jurong West St 42 Carpark
Third Party Claim Vehicle No : SLW 8113 S
Repair Cost For Vehicle No : SLH 40 A BMW X5

Estimate Supply of Parts & Labours

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Front bumper fascia	1	1,951.00	\$ 1,951.00
2	Front bumper clips	1 set	50.00	\$ 50.00
				<hr/> \$ 2,001.00

Labour Charges :-

	<u>Amounts</u>
Cut out, renew, knocking & welding front bumper, remove & install all damage parts, straighten & re-align body	\$ 380.00
Diagnostic & reset	\$ 300.00
Spray painting on damage parts	\$ 580.00
Sticker wrap on front bumper	\$ 580.00

Labour Charge	<hr/> \$ 1,840.00
Total Amount	<hr/> \$ 3,841.00

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.