

ASS. REC. BY: *marcus*

REF:

CC4/GRB21006052/UBS3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: *SLH 40A*Yr Regn: *04/11/16*Type: *M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /*

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: *Good / Fair / Poor / Burnt*Steering: *in order / Jammed / Leaked / Burnt or*Brake: *in order / Jammed / Leaked / Burnt or*Modi: *NI / S/Rim / STD A/Rim or*

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / *MIC* / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: *Frt / Rear / O/S / N/S / U/C / Rooftop or*The *U/C* / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

2)

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) \$ + RS ___ \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL

3/7/11 R/P # 980 confirmed with history

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLH40A/2105046

21st May 2021

The Manager
Motor Claim Department
India International Insurance Pte Ltd
64 Cecil Street
#04/05 IOB Building
Singapore 049711

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Allowed
2hr
P/P \$ 980/-
The whole Amount
2 days
29/6/21

Date of Accident : 19th May 2021
Location : Blk 543 Jurong West St 42 Carpark
Third Party Claim Vehicle No : SLW 8113 S
Repair Cost For Vehicle No : SLH 40 A BMW X5

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front bumper fascia R	1	1,951.00	\$ 1,951.00 X
2	Front bumper clips 11	1 set	50.00	\$ 50.00 X
				\$ 2,001.00

Labour Charges :-

	Amounts
Cut out, renew, knocking & welding front bumper, remove & install all damage parts, straighten & re-align body	\$ 380.00 280
Diagnostic & reset	\$ 300.00
Spray painting on damage parts	\$ 580.00 250
Sticker wrap on front bumper 2 day	\$ 580.00 450

Labour Charge

\$ 1,840.00

Total Amount

\$ 3,841.00

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

SGC AUTOGRAPHICS & SIGNS

Block 3015 Ubi Road 1 #01-268/270 Singapore 408704

Tel: 9019 6868, 6748 0982 Email: ggcstickers@gmail.com

Specialized in: Customized Vinyl Stickers, Car Decals, Signage.

Vehicle Corporate Imaging, Window film

ROC No: 53233865X

Cash Sales No: CS 13836

M/S: Specialists Motor Pte Ltd Date: 01/07/2021

PO No:

Quantity	Description	Unit Price S\$	Total Price S\$
	Repaste Bumper Stakes SLH40A		\$450.00
PAYNOW: 5323865X			Grand Total S\$ \$450.00

PAYNOW: 53233865X

Grand Total S\$

\$4.50.2

Pay by: Cash/Nets/Cheque No: _____