

BIFROST AUTO PTE LTD

No.8 Kaki Bukit Ave 4, Premier@ Kaki Bukit #01-49 Singapore 415875

Tel:+65 6452 4457

Fax:+65 6452 4584

Company Reg No. 201929175W

LKK Auto Consultants hereby notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

TP China.
Justin.**Estimate**

Code:

BF2021-0011

Date

12-May-21

Vehicle No.

SMY 317 B

Model

HONDA SHUTTLE

CHASSIS #

GP7-1218398

NO.	Particular	Quantity	Unit Price	Amount
LIST PRICE PARTS				
1	REAR BUMPER <i>Disturbed</i>	1		965 ✓ \$-00 1151
2	REAR BUMPER SIDE RETAINER L/R <i>Rit Dmgd</i>	2		39.30 ✓ \$-00 39.3
3	REAR BUMPER SIDE HOLDER L/R <i>new</i>	2		X \$-00 48.1
4	REAR BUMPER REFLECTOR RH <i>missing</i>	1		✓ \$-00 98.4
5	REAR BUMPER REFLECTOR GARNISH RH <i>missing</i>	1		✓ \$-00 38.4
6	REAR BUMPER INNER SPONGE <i>could</i>	1		✓ \$-00 94.1
7	REAR BUMPER REINFORCEMENT <i>new</i>	1		+ \$-00
8	REAR FENDER RH <i>Disturbed</i>	1	2978.40	1011 ✓ \$-00 1522.1
9	REAR FENDER GLASS RUBBER MOULDING RH <i>new</i>	1	2382.72	✓ \$-00 107.8
10	REAR FENDER INNER SHIELD RH <i>long</i>	1		✓ \$-00 194.1
11	REAR FENDER INNER TRIMBOARD RH <i>behind</i>	1		✓ \$-00 420.3
12	REAR FENDER AIR VENT RH <i>the new</i>	1		✓ \$-00 74.6
13	REAR DOOR RH <i>new</i>	1		+ \$-00 788.1
14	REAR DOOR MECHANISM LOCK RH <i>new</i>	1		+ \$-00 312.9
15	REAR DOOR CABIN WEATHER STRIP RH <i>new</i>	1		+ \$-00 321.1
SUB-TOTAL BEFORE DISCOUNT				\$-00
PERCENTAGE DISCOUNT 20%				\$-00
Sub-total 1				\$-00

NO.	SPECIAL NETT PRICE PARTS			
1	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$30.00	✓ \$30.00
2	REAR FENDER INNER SHIELD CLIPS(SET) RH <i>new</i>	1	120 \$30.00	20 ✓ \$30.00
3	REAR FENDER INNER TRIMBOARD CLIPS(SET) RH <i>new</i>	1	\$30.00	✓ \$30.00
4	REAR FENDER GLASS SEALANT <i>new</i>	1	\$80.00	40 ✓ \$80.00
Sub-total 2				\$170.00

LABOUR				
1	To diagnose, replace/or repair on the rear portion electrical system for proper functioning and where consistent to the accident	1	\$160.00	\$160.00 30
2	To remove, reinstall roof top upholstery, trim garnish, trim liner carpet(to FR)	1	\$140.00	\$140.00 60
3	To respray, painting on the change bodyparts, repair portion and where consistent to the accident	1	\$1,000.00	\$1,000.00 600
4	To provide labour, workmanship to change damaged	1	\$1,250.00	\$1,250.00 600

Advianty
2/5 20/05/21 asaya

bodyparts, repair, align body structure & damaged
and where consistent to the accident

5 To apply anti-rust chemical on repaired & replaced panel
and where consistent to the accident

1

\$180.00

\$180.00

60

Sub-total 3

\$2,730.00

Total for Parts & Labour

\$2,900.00

Adrian Lj

L/s 20/05/21 05 Days

Supplementary : 332.88.

total: 4185.60

L/s: 3.3K

BIFROST AUTO PTE LTD

No.8 Kaki Bukit Ave 4, Premier@ Kaki Bukit #01-49 Singapore 415875

Tel:+65 6452 4457

Fax:+65 6452 4584

Company Reg No. 201929175W

SUPPLEMENTARY

Code:

BF2021-0014

Date

22/05/2021

Vehicle No.

SMY 317 B

Model

HONDA SHUTTLE

CHASSIS #

NO.	Particular	Quantity	Unit Price	Amount
LIST PRICE PARTS				
1	REAR TAILLAMP RH <i>Crushed</i>	1	\$410.20	\$410.20 ✓
2	REAR TAILLAMP STAY CLIP RH <i>sw</i>	1	\$5.90	\$5.90 ✓
SUB-TOTAL BEFORE DISCOUNT				\$416.10
PERCENTAGE DISCOUNT 20%				\$83.22
Sub-total 1				<u>\$332.88</u>
SPECIAL NETT PRICE PARTS				
			\$-00	\$-00
Sub-total 2				<u>\$-00</u>
LABOUR				
Sub-total 3				\$0.00
Total for Parts & Labour				\$332.88

Supply: 416.10
Less 20% : 332.88