



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2107104

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 14/10/2021
Reference CC4/FCI21006058/Aea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. PC 8973J

Insured Veh. SG 5116E

Claim No. D21001556MFBP

Policy No. D-20096309MFBP

Accident Date 14/05/2021

Inspection Date 02/06/2021

Description	Total
Survey Inspection	198.00
Digital Photographs	
Transportation	
Subtotal	198.00
GST (7%)	13.86
Grand Total	211.86

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21006058/Aea3q2	
			Date: 14/10/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SG 5116E	Veh. Inspected	PC 8973J	
Policy No.	D-20096309MFBP	Coverage (\$)	0.00	
Claim No.	D21001556MFBP	Excess (\$)	0.00	
Assign From	ESTHER	Assign Date	21/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2754	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	GDH2232001900	Colour	WHITE	
Odometer	88485 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	DURATURN	6 mm	
L/H Front Tyre	195 R15C	DURATURN	6 mm	
R/H Rear Tyre	195 R15C	DURATURN	6 mm	
L/H Rear Tyre	195 R15C	DURATURN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/05/2021	Inspection Date	02/06/2021	
Survey held at	KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 8973J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR ROOF SIDE PANEL	TO REPAIR SEE LABOUR	1,856.90	-
1	REAR WINDOW GLASS	NOT NECESSARY	895.60	-
1	REAR WINDOW GLASS SEAL	NOT NECESSARY	158.30	-
			2,910.80	-
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR ROOF SIDE PANEL .		1,000.00	100.00
	TO REMOVE AND INSTALL REAR WINDOW GLASS .	NOT NECESSARY	150.00	-
	SPRAY PAINTING.		1,000.00	300.00
			2,150.00	400.00
	GRAND TOTAL		5,060.80	400.00
RECOMMENDED COST OF REPAIRS				400.00

Report Ref No. CC4/FCI21006058/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PC 8973J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

