

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0432/2021/NK
DATE : 19-May-21
WIP : 27764

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 21/5/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

3 days - ok - Johnny Boo

16-Jul-21

OWNER'S NAME : MR. TAN TECK LENG
ADDRESS : BLK 240 PASIR RIS STREET 21
#05-47
SINGAPORE 510240
TELEPHONE : HP +65 97592235
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700033517-03
VEHICLE NO : **SLR 227 B**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI
MODEL YEAR : 28/7/2017
ENGINE NO : CVN 039073
CHASSIS NO : WAUZZZF48HA165499
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-May-21
PLACE OF ACCIDENT : BLK 235A PASIR RIS ST 21
MULTI STORY CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLR 227 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNES FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	
2	TO DISMANTLE AND RENEW FRONT BUMPER.REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	\$ 500.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,000.00	\$ 550.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	3,722.00	\$ 1,242.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLR 227 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,111.00	\$	1,688.80
2	FRONT BUMPER FIXING PARTS	1	TBC		
3	FRONT BUMPER SECURING STRIP	2	\$ 71.00		
4	FRONT BUMPER LOWER SATIN GRILLE CENTRE	1	\$ 196.00		
5	FRONT BUMPER CLOSING ELEMENT LOWER CENTRE	1	\$ 210.00	\$	167.60
6	FRONT BUMPER AIR GUIDE RH	1	\$ 63.00		
7	FRONT RADIATOR GRILLE	1	\$ 1,152.00		
8	FRONT BUMPER AIR GUIDE GRILLE RH	1	\$ 135.00	\$	108.00
9	FRONT BUMPER FOAM	1	\$ 124.00	\$	99.20
10	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 846.00		
11	FRONT BUMPER TOP COVER	1	\$ 127.00		
12	FRONT BUMPER GUIDE SECTION RH	1	\$ 38.00	\$	29.84
13	"CAUTION" SIGN	1	\$ 14.00		
14	AIRCON STICKER	1	\$ 8.00		
15	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 138.00		
16	FRONT BUMPER SUPPORT LH / RH	2	\$ 58.00		
17	WHEEL HOUSING LINER RH	1	\$ 241.00	\$	192.80
18	WHEEL HOUSING LINERS ATTACHEMENTS PARTS	1	TBC		
19	WHEEL SPOILER RH	1	\$ 36.00	\$	28.56
20	WHEEL SPOILER TRIM RH	1	\$ 73.00	\$	58.40
SUB SPARE PARTS		:	\$ 5,641.00	\$	2,373.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLR 227 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
				\$ 2,373.20
21	AIR GUIDE COVER INNER RH	1	\$ 28.00	
22	AIR GUIDE COVER OUTER RH	1	\$ 12.00	
23	AIR GUIDE	1	\$ 16.00	
24	AIR GUIDE COVER LOWER	1	\$ 22.00	
25	NOISE INSULATION	1	\$ 572.00	
26	SUNDRIES	1	\$ 300.00	\$ 31.36
TOTAL SPARE PARTS		:	\$ 6,591.00	\$ 2,404.56
TOTAL LABOUR CHARGES		:	\$ 3,722.00	\$ 1,242.00
GRAND TOTAL		:	\$ 10,313.00	\$ 3,646.56

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT