

Car-in

16/6/21

mp= 27764



# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

LQ/TOH

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLR 227 B

HIA-Asham

3 days

| S/N             | PARTS DESCRIPTION                                  | QTY | DAMAGED PARTS & PRICES |       | REMARKS |
|-----------------|----------------------------------------------------|-----|------------------------|-------|---------|
|                 |                                                    |     | S/NETT                 |       |         |
| 1               | FRONT BUMPER Distorted                             | 1 S | 2,111.00               | ✓     |         |
| 2               | FRONT BUMPER FIXING PARTS New                      | 1   | TBC                    | +     |         |
| 3               | FRONT BUMPER SECURING STRIP New                    | 1 S | 21.00                  | 36.00 |         |
| 4               | FRONT BUMPER LOWER SATIN GRILLE CENTRE New         | 1 S | 196.00                 | x     |         |
| 5               | FRONT BUMPER CLOSING ELEMENT LOWER CENTRE Canceled | 1 S | 210.00                 | 2     |         |
| 6               | FRONT BUMPER AIR GUIDE RH <del>Distorted</del> New | 1 S | 63.00                  | +     |         |
| 7               | FRONT RADIATOR GRILLE New                          | 1 S | 1,152.00               | x     |         |
| 8               | FRONT BUMPER AIR GUIDE GRILLE RH Canceled          | 1 S | 135.00                 | 2     |         |
| 9               | FRONT BUMPER FOAM <del>Not New</del> Canceled      | 1 S | 124.00                 | +     |         |
| 10              | FRONT BUMPER REINFORCEMENT BEAM New                | 1 S | 846.00                 | x     |         |
| 11              | FRONT BUMPER TOP COVER New                         | 1 S | 127.00                 | +     |         |
| 12              | FRONT BUMPER GUIDE SECTION RH Damaged              | 1 S | 38.00                  | ✓     |         |
| 13              | "CAUTION" SIGN } New                               | 1 S | 14.00                  | +     |         |
| 14              | AIRCON STICKER } New                               | 1 S | 8.00                   | +     |         |
| 15              | FRONT BUMPER LOCK CARRIER BRACKET New              | 1 S | 138.00                 | +     |         |
| 16              | FRONT BUMPER SUPPORT LH / RH ?                     | 2 S | 58.00                  | ?     |         |
| 17              | WHEEL HOUSING LINER RH Torn                        | 1 S | 241.00                 | ✓     |         |
| 18              | WHEEL HOUSING LINERS ATTACHEMENTS PARTS New        | 1   | TBC                    | x     |         |
| 19              | WHEEL SPOILER RH Canceled                          | 1 S | 36.00                  | ✓     |         |
| 20              | WHEEL SPOILER TRIM RH Canceled                     | 1 S | 73.00                  | ✓     |         |
| SUB SPARE PARTS |                                                    |     | : \$ 5,641.00          |       |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

Adrian Li  
H.S.  
Resigned