

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0401/2021/HR
DATE : 6-May-21
WIP : 25776

Denise.

\$17016.56.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY SAME AS REPAIR DATE.

YOUR INSURED VEH NO : SGJ 498 L

A.G ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS NEO CHIAU YEN
ADDRESS : 57A LORONG TELOK KURAU
SINGAPORE S425185
TELEPHONE : HP +65 96681449
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070032096
VEHICLE NO : ~~SMS 6884 H~~ *sms 6684 H.*
MODEL CODE : A1 SB S LINE 1.0 TFS
MODEL YEAR : 9/3/2020
ENGINE NO : DKJ 048538
CHASSIS NO : WAUZZZGB0LR023798
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-May-21
PLACE OF ACCIDENT : NEAR JURONG WEST

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 6684 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER DATA REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO FUNCTION. S/N S	280.00 ✓	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR REVERSE CAMERA. S/N S	360.00 ✓	✓
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO COMPONENTS. S/N S	480.00 ✓	✓
4	TO DISMANTLE REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR OUTER AND INNER CROSS PANELS. RENEW REAR BUMPER AND REAR LID. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. S	3,500.00 2000	2500 
5	TO RESPRAY REAR BUMPER, REAR LID AND END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT. S	2,600.00 1650	✓
6	TO RENEW REAR WINDSCREEN S/N S	360.00 ✓	✓
SUB LABOUR CHARGES		: \$ 7,580.00	

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 6684 H

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
				400
7	TO INSTALL 3M REAR WINDSCREEN SOLAR FILM.	S/N	TBC	✓
8	TO REMOVE AND RENEW REAR EXHAUST SILENCER. ALIGN TO POSITION.	S/N S	480.00	7 X
9	TO CARRY OUT DIAGNOSTIC CHECK.	S	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 8,252.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 6684 H

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	REAR BUMPER Distorted	1	S	✓ 2,179.00	✓	1743.2
2	REAR BUMPER ADAPTER - LH / RH Not Nec	2	S	✗ 44.00	✗	336.8
3	REAR BUMPER DIFFUSER Distorted	1	S	✓ 421.00	✓	181.2
4	REAR BUMPER GRILLE - LH / RH LH cracked	2	S	✓ 454.00	22	170.8
5	REAR BUMPER TRIM - CENTER Distorted	1	S	✓ 214.00	✓	68.64
6	REAR BUMPER GRILLE - CENTER Distorted	1	S	✓ 86.00	✓	
7	REAR BUMPER LIGHT REFLECTOR - LH / RH LH dented	2	S	✓ 60.00	✗	424
8	REAR BUMPER REINFORCEMENT BEAM cra	1	S	✓ 530.00	✓	108
9	REAR BUMPER SECURING STRIP - CENTER cra	1	S	✓ 135.00	✓	35.86 38.56
10	REAR BUMPER GUIDE SECTION - LH cra	1	S	✓ 49.00	✓	44.24
11	REAR BUMPER GUIDE PROFILE - LH	1	S	✓ 56.00	✓	
12	REAR PARKING AID SENSOR Not Nec	2	S	✗ 976.00	✗	
13	REAR PARKING AID SENSOR SEAL RING Not Nec	4	S	✗ 9.00	✗	
14	REAR BUMPER WIRING SET Not Nec	1	S	✗ 182.00	✗	
15	REAR BUMPER AERIAL ANTENNA Not Nec	1	S	✓ 71.00	✗	2448.8
16	REAR BOOT LID Dented	1	S	✓ 3,061.00	✓	
17	REAR BOOT LID PACKING ADHESIVE Not Nec	1	S	✗ 19.00	✗	
18	REAR BOOT LID ATTACHMENT PARTS Not Nec	1	S	✓ 387.00	✗	31.20
19	REAR BOOT LID BALL STUD Not Nec	2	S	✓ 39.00	✓	
20	REAR BOOT LID GASKET Not Nec	1	S	✓ 155.00	✗	
SUB TOTAL SPARE PARTS		:	\$	9,127.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL 6366 2323 FAX 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 6684 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	REAR BOOT LID LOCK <i>Not New</i>	1	\$	178.00	+
22	REAR BOOT LID STRIKER PLATE	1	\$	59.00	+
23	REAR BOOT LID LOCK ACTUATOR <i>Not New</i>	1	\$	177.00	+
24	REAR BOOT LID BUNGS	2	\$	4.00	2.88
25	REAR BOOT LID CLIP <i>new</i>	2	\$	3.00	2.4
26	REAR BOOT LID PACKING ADHESIVE <i>Repacked</i>	1	\$	19.00	14.88
27	REAR BOOT LID BUNGS <i>Not New</i>	1	\$	4.00	+
28	"AUDI" EMBLEM <i>Not New</i>	1	\$	138.00	110
29	"A1" EMBLEM <i>Not New</i>	1	\$	99.00	79.04
30	REAR LICENSE PLATE LIGHT <i>Not New</i>	2	\$	202.00	645.6
31	TAIL LIGHT INNER - LH <i>Not New</i>	1	\$	807.00	+
32	TAIL LIGHT TRIM - LH <i>Not New</i>	1	\$	30.00	+
33	TAIL LIGHT OUTER - LH <i>Not New</i>	1	\$	807.00	645.6
34	TAIL LIGHT CLIP <i>Not New</i>	5	\$	8.00	6
35	REAR BUMPER SPOILER CLIP <i>Not New</i>	2	\$	15.00	12
36	REAR WINDOW <i>Not New</i>	1	\$	776.00	620.4
37	REAR WINDOW PACKING ADHESIVE <i>Not New</i>	4	\$	61.00	48.8
38	REAR WINDOW BONDING AGENT <i>Not New</i>	1	\$	49.00	38.48
39	REAR CROSS PANEL <i>Dented</i>	1	\$	271.00	216.8
40	REAR CROSS PANEL REINFORCEMENT <i>Dented</i>	1	\$	637.00	510
SUB TOTAL SPARE PARTS		:	\$	4,344.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL 6366 2323 FAX 6641 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 6684 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
	crs			107.52
41	REAR VENT TRIM - CENTRE	2	\$ 135.00	✓
42	REAR SILENCER <i>Rem</i>	1	\$ 466.00	X
43	REAR SILENCER DUAL CLIP <i>Rem</i>	1	\$ 59.00	X
44	REAR SILENCER RETAINER <i>Rem</i>	1	\$ 55.00	X
45	WINDSCREEN SEALANT <i>Rem</i>	S/N	\$ 200.00	200
46	ACRYLIC SEALER <i>Nec</i>	S/N	\$ 180.00	180
47	CAVITY WAX <i>Nec</i>	S/N	\$ 140.00	140
48	STONE CHIP <i>Nec</i>	S/N	\$ 180.00	180
49	REAR NUMBER PLATE WITH HOLDER <i>deduct</i>	S/N	\$ 60.00	60
50	SUNDRIES <i>Nec</i>	S/N	\$ 300.00	70.72
TOTAL SPARE PARTS		:	\$ 15,246.00	
TOTAL LABOUR CHARGES		:	\$ 8,252.00	
GRAND TOTAL		:	\$ 23,498.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA.KHAI@PRFMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian King.
21/05/21

Not Authorised, 05 Days

12 Days
H.G.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey below after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0401/2021/HR 27-Aug-21 GLORY 1 of 1 SMS 6684 H AUDI A1 SB S-LINE 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Labour</u>			
1	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00	\$ 150.00
GRAND TOTAL		\$ 200.00	\$ 150.00

For Premium Automobiles Pte Ltd

 Authorised Signature