

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate - 1

Denise.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/TP/0401/2021/HR

28-Jun-21

CHANG

1 of 1

SMS 6684 H

AUDI A1 SB S-LINE 1.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO REPAIR SPARE WHEEL HOUSING.	\$ 700.00	250 ✓
2	TO RESPRAY SPARE WHEEL HOUSING.	\$ 1,050.00	550 ✓
<u>Parts</u>			
1	REAR WHEEL HOUSING LINER - LH <i>torn</i>	\$ 183.00	✓ 146
2	REAR UNDERBODY TRIM - LH <i>torn</i>	\$ 47.00	✓ 39.36
3	WEBBING ADHESIVE TAPE <i>N/A</i>	\$ 127.00	✓ 104.8
4	REAR END PANEL CONNECTING PLATE - LH/RH <i>N/A</i>	\$ 82.00	✓ 67.84
GRAND TOTAL		\$ 2,189.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Lj

28/06/21.

sls.

Add 1 day

Car-in

24/6/21

mp 25776

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Kiam



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 6684 H

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER Distorted	1	S 2,179.00	✓
2	REAR BUMPER ADAPTER - LH / RH	2	S 44.00	?
3	REAR BUMPER DIFFUSER Distorted	1	S 421.00	✓
4	REAR BUMPER GRILLE - LH / RH LH cracked	2	S 454.00	227.
5	REAR BUMPER TRIM - CENTER Distorted	1	S 214.00	✓
6	REAR BUMPER GRILLE - CENTER Distorted	1	S 86.00	✓
7	REAR BUMPER LIGHT REFLECTOR - LH / RH LH ?	2	S 60.00	?
8	REAR BUMPER REINFORCEMENT BEAM Dented	1	S 530.00	✓
9	REAR BUMPER SECURING STRIP - CENTER	1	S 135.00	✓
10	REAR BUMPER GUIDE SECTION - LH	1	S 49.00	✓
11	REAR BUMPER GUIDE PROFILE - LH	1	S 56.00	✓
12	REAR PARKING AID SENSOR	2	S 976.00	?
13	REAR PARKING AID SENSOR SEAL RING	4	S 9.00	?
14	REAR BUMPER WIRING SET	1	S 182.00	✓
15	REAR BUMPER AERIAL ANTENNA	1	S 71.00	?
16	REAR BOOT LID Dented	1	S 3,061.00	✓
17	REAR BOOT LID PACKING ADHESIVE	1	S 19.00	✓
18	REAR BOOT LID ATTACHMENT PARTS	1	S 387.00	✓
19	REAR BOOT LID BALL STUD	2	S 39.00	✓
20	REAR BOOT LID GASKET	1	S 155.00	✓
SUB TOTAL SPARE PARTS		:	S 9,127.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Add

870 827

310

A

-

2

AGS - Adrian

8 days

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 6684 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR BOOT LID LOCK <i>Not New</i>	1	\$ 178.00	+
22	REAR BOOT LID STRIKER PLATE	1	\$ 59.00	+
23	REAR BOOT LID LOCK ACTUATOR <i>Not New</i>	1	\$ 177.00	+
24	REAR BOOT LID BUNGS	2	\$ 4.00	+
25	REAR BOOT LID CLIP <i>New</i>	2	\$ 3.00	+
26	REAR BOOT LID PACKING ADHESIVE <i>Repacked</i>	1	\$ 19.00	+
27	REAR BOOT LID BUNGS <i>Not New</i>	1	\$ 4.00	+
28	"AUDI" EMBLEM <i>Not New</i>	1	\$ 138.00	✓
29	"A1" EMBLEM <i>Not New</i>	1	\$ 99.00	✓
30	REAR LICENSE PLATE LIGHT <i>New</i>	2	\$ 202.00	+
31	TAIL LIGHT INNER - LH <i>Cracked</i>	1	\$ 807.00	✓
32	TAIL LIGHT TRIM - LH <i>New</i>	1	\$ 30.00	+
33	TAIL LIGHT OUTER - LH <i>New</i> <i>wt</i>	1	\$ 807.00	✓
34	TAIL LIGHT CLIP <i>New</i>	5	\$ 8.00	+
35	REAR BUMPER SPOILER CLIP <i>New</i>	2	\$ 15.00	✓
36	REAR WINDOW <i>New</i>	1	\$ 776.00	✓
37	REAR WINDOW PACKING ADHESIVE <i>New</i>	4	\$ 61.00	✓
38	REAR WINDOW BONDING AGENT <i>New</i>	1	\$ 49.00	✓
39	REAR CROSS PANEL <i>Dented</i>	1	\$ 271.00	✓
40	REAR CROSS PANEL REINFORCEMENT <i>Dented</i>	1	\$ 637.00	✓
SUB TOTAL SPARE PARTS		:	\$ 4,344.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 6684 H

S/N	PARTS DESCRIPTION	QTY		DAMAGED PARTS & PRICES	
				S/NETT	REMARKS
41	REAR VENT TRIM - CENTRE <i>cracked</i>	2	\$	135.00	✓
42	REAR SILENCER	1	\$	466.00	?
43	REAR SILENCER DUAL CLIP	1	\$	59.00	?
44	REAR SILENCER RETAINER	1	\$	55.00	?
45	WINDSCREEN SEALANT <i>new</i>	S/N	\$	200.00	✓
46	ACRYLIC SEALER <i>Nec</i>	S/N	\$	180.00	✓
47	CAVITY WAX <i>Nec</i>	S/N	\$	140.00	✓
48	STONE CHIP <i>Nec</i>	S/N	\$	180.00	✓
49	REAR NUMBER PLATE WITH HOLDER <i>dented</i>	S/N	\$	60.00	✓
50	SUNDRIES	S/N	\$	300.00	?
TOTAL SPARE PARTS		:	\$	15,246.00	
TOTAL LABOUR CHARGES		:	\$	8,252.00	
GRAND TOTAL		:	\$	23,498.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Adrian Lj
28/06/21