



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0356/2021/HR
DATE : 24-Apr-21
WIP : 24397

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : ACW HOLDINGS P/L
ADDRESS : 20 PENJURU LANE
#06-01
SINGAPORE 609193
TELEPHONE : HP +65 91542323
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070149996
VEHICLE NO : **SMV 9077 A**
MODEL CODE : Q5 SPORT 2.0 TFSI qu
MODEL YEAR : 27/10/2020
ENGINE NO : DAX 061683
CHASSIS NO : WAUZZZFXYL2005422
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Apr-21
PLACE OF ACCIDENT : NEAR PIE NEAR BKE EXIT



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 9077 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER BOTH HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	\$ 00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET AND FRONT WHEEL ARCH TRIMS.	\$ 3,400.00	550 Bumper Wheel Arch x 2 = 400 <u>950</u>
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,072.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9077 A

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>Defend</i>	1	\$	<u>2,929.00</u>	
2	FRONT BUMPER FIXING PARTS <i>Not new</i>	1	\$	293.00	x
3	FRONT BUMPER SECURING STRIP - LH / RH ?	2	\$	56.00	?
4	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>Not new</i>	2	\$	226.00	x
5	FRONT BUMPER GRILLE - CENTER <i>Not new</i>	1	\$	144.00	x
6	FRONT BUMPER SPOILER <i>Not new</i>	1	\$	763.00	x
7	FRONT BUMPER UNDERRUN BAR <i>new</i>	1	\$	518.00	x
8	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$	173.00	+
9	FRONT RADIATOR GRILLE <i>Conclud</i>	1	\$	3,530.00	✓
10	"QUATTRO" EMBLEM <i>new</i>	1	\$	106.00	✓
11	FRONT BUMPER STRIKER PLATE ?	1	\$	244.00	?
12	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>RH missing</i>	2	\$	1,162.00	581
13	FRONT BUMPER END CAP - LH / RH <i>RH missing</i>	2	\$	184.00	92
14	FRONT BUMPER LOCKING CLIP ?	4	\$	16.00	?
15	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	1	\$	177.00	x
16	FRONT BUMPER CARRIER <i>Not new</i>	1	\$	981.00	x
17	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$	78.00	x
18	FRONT BUMPER COVER <i>?</i>	1	\$	129.00	x
19	"CAUTION" STICKER <i>?</i>	1	\$	14.00	x
20	AIR CONDITIONER STICKER <i>?</i>	1	\$	20.00	x
SUB TOTAL SPARE PARTS			\$	<u>11,743.00</u>	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9077 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT INNER PARKING AID SENSOR	2	\$ 488.00	+
22	FRONT INNER PARKING AID SENSOR SEAL RING	4	\$ 14.00	+
23	FRONT HORN LOW / HIGH TONE - LH / RH	2	\$ 390.00	+
24	HEADLIGHT MOUNTING - LH / RH	2	\$ 236.00	+
25	HEADLIGHT - LH / RH	2	\$ 16,382.00	+
26	HEADLIGHT LIFT CYLINDER - LH / RH	2	\$ 280.00	+
27	HEADLIGHT HOSE	1	\$ 125.00	+
28	FRONT WHEEL SPOILER - LH / RH	2	\$ 324.00	+
29	FRONT WHEEL COVER - LH / RH	2	\$ 1,264.00	✓
30	FRONT RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 96.00	+
31	FRONT RADIATOR AIR GUIDE - CENTER	1	\$ 42.00	+
32	FRONT RADIATOR AIR GUIDE LONG - LH / RH	2	\$ 116.00	+
33	FRONT NUMBER PLATE	S/N	\$ 60.00	✓
34	SUNDRIES		\$ 350.00	?
TOTAL SPARE PARTS		:	\$ 31,910.00	
TOTAL LABOUR CHARGES		:	\$ 6,072.00	
GRAND TOTAL		:	\$ 37,982.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Handwritten notes: A bracket groups items 21-27 with the note "Not Nec". Item 28 has "Not in". Item 29 has "Xlar". Items 30-32 have a bracket with "Not in". Item 33 has "Dented".



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Lj
SURVEYED DATE : 21/03/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 03 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT