

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0356/2021/HR
DATE : 24-Apr-21
WIP : 24397

Xiao Chen

9277.20

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : ACW HOLDINGS P/L
ADDRESS : 20 PENJURU LANE
#06-01
SINGAPORE 609193
TELEPHONE : HP +65 91542323
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070149996
VEHICLE NO : **SMV 9077 A**
MODEL CODE : Q5 SPORT 2.0 TFSI qu
MODEL YEAR : 27/10/2020
ENGINE NO : DAX 061683
CHASSIS NO : WAUZZZFYXL2005422
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Apr-21
PLACE OF ACCIDENT : NEAR PIE NEAR BKE EXIT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHA1@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 9077 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$	480.00	✓ ✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER BOTH HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	500 ✓
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET AND FRONT WHEEL ARCH TRIMS.	\$	3,400.00	950 550 Bumper Wheel Arch x2 = 400
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓ ✓ 950 ✓
TOTAL LABOUR CHARGES		:	\$ 6,072.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 3, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1193
 [EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG]

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9077 A

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	FRONT BUMPER <i>Dehd</i>	1	\$ 2,929.00		2342.80	
2	FRONT BUMPER FIXING PARTS <i>Not nec</i>	1	\$ 293.00	*		
3	FRONT BUMPER SECURING STRIP - LH / RH <i>Not nec</i>	2	\$ 56.00	?	X	
4	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>Not nec</i>	2	\$ 226.00	*		
5	FRONT BUMPER GRILLE - CENTER <i>Not nec</i>	1	\$ 144.00	*		
6	FRONT BUMPER SPOILER <i>Not nec</i>	1	\$ 763.00	*		
7	FRONT BUMPER UNDERRUN BAR <i>Not nec</i>	1	\$ 518.00	*		
8	FRONT BUMPER CLOSING ELEMENT <i>Not nec</i>	1	\$ 173.00	*		
9	FRONT RADIATOR GRILLE <i>Cracked</i>	1	\$ 3,530.00	✓	2824	
10	"QUATTRO" EMBLEM <i>Not nec</i>	1	\$ 106.00	✓	84.80	
11	FRONT BUMPER STRIKER PLATE <i>Not nec</i>	1	\$ 244.00	X		
12	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>LH out RH missing</i>	2	\$ 1162.00	1,162.00	464.40	
13	FRONT BUMPER END CAP - LH / RH <i>RH missing</i>	2	\$ 184.00	92	73.20	
14	FRONT BUMPER LOCKING CLIP <i>Not nec</i>	4	\$ 16.00	?	X	
15	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	1	\$ 177.00	X	✓	141.60
16	FRONT BUMPER CARRIER <i>Not nec</i>	1	\$ 981.00	*		
17	FRONT BUMPER GUIDE SECTION - LH / RH <i>Not nec</i>	2	\$ 78.00	*		
18	FRONT BUMPER COVER	1	\$ 129.00	*		
19	"CAUTION" STICKER <i>Not nec</i>	1	\$ 14.00	*		
20	AIR CONDITIONER STICKER	1	\$ 20.00	*		
SUB TOTAL SPARE PARTS			\$ 11,743.00			

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9077 A

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT INNER PARKING AID SENSOR	2	\$ 488.00	+
22	FRONT INNER PARKING AID SENSOR SEAL RING	4	\$ 14.00	+
23	FRONT HORN LOW / HIGH TONE - LH / RH	2	\$ 390.00	+
24	HEADLIGHT MOUNTING - LH / RH	2	\$ 236.00	X
25	HEADLIGHT - LH / RH	2	\$ 16,382.00	+
26	HEADLIGHT LIFT CYLINDER - LH / RH	2	\$ 280.00	+
27	HEADLIGHT HOSE	1	\$ 125.00	+
28	FRONT WHEEL SPOILER - LH / RH	2	\$ 324.00	+
29	FRONT WHEEL COVER - LH / RH	2	\$ 1,264.00	✓
30	FRONT RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 96.00	+
31	FRONT RADIATOR AIR GUIDE - CENTER	1	\$ 42.00	+
32	FRONT RADIATOR AIR GUIDE LONG - LH / RH	2	\$ 116.00	+
33	FRONT NUMBER PLATE	S/N	\$ 60.00	✓
34	SUNDRIES		\$ 350.00	?
TOTAL SPARE PARTS		:	\$ 31,910.00	
TOTAL LABOUR CHARGES		:	\$ 6,072.00	
GRAND TOTAL		:	\$ 37,982.00	

RH deformed

Not
NOL

Not in
Xla

2
NOL

Deformed

Nec

[Signature]

8/19/15

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Lj
SURVEYED DATE : 21/05/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 03 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT