

Enquire Vehicle's Insurance Particulars

Enquire Vehicle's Insurance Particulars (As At 19 Sep 2020 / 15:35:00)

Vehicle Insurance Details



Vehicle No.:

GBB4130Y

Make Description/Model:

TOYOTA / HIACE MANUAL

Insurance Company Name:

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Business Transaction Reference No.:

20200921155157869715

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).

Save as PDF

OK →

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/09/2020 15:27
Date Of Accident	19/09/2020 15:30
Exact Location Of Accident	AYE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBK4606U
Insured/Policyholder	
Name Of Registered Owner	UNICO TOTAL SOLUTION PTE. LTD
Co Reg No	2XXXXX247K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	DELIVERY
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	2070116721
Cover Note Number	

Driver

Name of Driver	YUAN HAINING
Passport No/FIN	GXXXX733K
Date Of Birth	24/11/1982
Occupation	OUTDOOR
Date Of Driving Pass	17/04/2018
Driving Experience	2 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81586718
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

在 19/9/2020 3.35pm 我直走向 Tuas 方向走，
突然 GBB 4130 Y 撞上我的车后面。

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder
Date & Time:




Driver's Signature
(If driver is not the policyholder)

Duan hai nong

Reporting Centre Personnel's Signature
Name:

R

Accident Photo



CARLINK CONSULTANCY

60 Hillside Drive, Singapore 549009

Fax: 62874788 Tel: 62856178

INVOICE

M/S Unico Total Solution Pte Ltd
C/o 27A Jurong Port Road. #01-30
Singapore 619101

Invoice No: CL 12192 TP
Our Ref: CL 12192 GBK 4606 U
Date: 2nd February 2021

S/N	DESCRIPTION	QTY	UNIT PRICE (\$)	AMOUNT (\$)
1	<u>Vehicle No: GBK 4606 U</u> Charges for accident vehicle inspection and appraisal report, transportation, photographs & misc*** (photographs - 216 copies)			\$991.00
			Total:	\$991.00

We thank you for the opportunity to serve you and assure you of our best at all times


PATRICK NG
Automotive Engineer Assessor
MIMI, MRTE, LCGI, I ENG, LAE, CGLIFTC

Note: Payment by cheque should be crossed and made payable to "CARLINK CONSULTANCY"

CARLINK CONSULTANCY


60 Hillside Drive
Singapore 549009

Tel : 62856178

Fax : 62874788

ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT

Our Ref: CL 12192 GBK 4606 U

1 REFERENCE			
Date of request	:	22nd September 2020	
Requested by	:	M/S Unico Total Solution Pte Ltd C/o 27A Jurong Port Road #01-30 Singapore 619101	
Type of claim	:	Third party	
Workshop	:	M/S Sin Foo Hing Battery Service 27A Jurong Port Road, #01-30 Singapore 619101	
Date of survey	:	22nd September 2020	
Accident date	:	19th September 2020	
2 DETAILS OF VEHICLE			
Registration No.	:	GBK 4606 U	
Make & Model	:	Toyota Dyna 150 5MT	
Date of registration	:	7th August 2020	
Engine No.	:	1KDB040432	
Chassis No.	:	JTFAT35Y90K215299	
Speedometer reading	:	4658 Km	
Transmission	:	Manual	
Colour	:	White	
3 STATIC CHECK			
Steering	:	see annex(es)	Paintwork : Good
Footbrake	:	see annex(es)	Modification : Nil
Handbrake	:	see annex(es)	General condition : Good
4 TYRE CONDITION			
		<u>Nearside/Make</u>	<u>Offside/Make</u> <u>Size</u>
Front tyre	:	7mm/Bridgestone	7mm/Bridgestone : 195/75 R15
Rear tyre	:	7mm/Bridgestone	7mm/Bridgestone : 155 R15
5 POINT OF IMPACT			
See Annex(es) and Motor Accident Reports			
6 REMARK			
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.			

Annex A : Assesement / Adjustment on Spare Parts

GBK 4606 U

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)	
S/Nett Items							
1	Rear cold box door assy RH	Grazed/dented/warped	1	\$1,900.00		\$1,900.00	X SVC
2	Rear cold box door assy rubber seal RH	Cut	1set	\$400.00		\$400.00	/
3	Rear cold box door hinges RH	Bent	2	\$500.00		\$500.00	400 /
4	Rear cold box door design sticker c/w company logo, Monzone sticker, Unico, lettering sticker and etc	Grazed/dented/cut	1	\$600.00		\$600.00	X SVC
5	Rear door frame aluminium alloy panel RH (Vertical)	Serviceable	1	\$1,500.00		\$0.00	
6	Rear end panel aluminium alloy panel	Dented/bent/cut	1	\$1,800.00		\$1,800.00	/
7	Rear end panel foam insulated sandwich panel	Bent	1	\$850.00		\$850.00	/
8	Rear end panel insulated foam	Necessary	1	\$400.00		\$400.00	300 /
9	Rear end panel reflective Caution sticker	Necessary	1	\$150.00		\$150.00	100 /
10	Rear chassis override rubber bumper stopper	Deformed/cut	2	\$360.00		\$360.00	300 /
11	Rear chassis end cross member	Bent	1	\$550.00		\$550.00	X R
12	Rear RH chassis frame top cushion pad	Shifted/cut	1	\$180.00		\$180.00	X SVC
13	Rear bumper c/w bracket	Slack/buckled	1set	\$1,800.00		\$1,800.00	1300 /
14	Rear number plate	Dented/bent	1	\$38.00		\$38.00	/
15	Rear number plate lamp RH	Cracked	1	\$68.00		\$68.00	X SVC
16	Rear reverse camera c/w LED light	Cracked/faulty	1	\$750.00		\$750.00	500 /
17	Reverse sensors c/w control unit	Distorted/faulty	1set	\$360.00		\$360.00	200 /
18	Tail lamp RH	Cracked	1	\$250.00		\$250.00	/
19	Tail lamp bracket RH	Bent	1	\$85.00		\$85.00	/
20	Silicone white sealer	Necessary	2	\$160.00		\$160.00	/
21	Sika glue	Necessary	1	\$180.00		\$180.00	/
Total for Spare Parts :						\$12,881.00	\$11,381.00

Annex B : Adjustment on Labour and Spray Painting

GBK 4606 U

Item	Job Description	Workshop Est. (\$)	Adjusted Cost (\$)	
1	To check wiring system & lights operation	\$150.00	\$100.00	50 ✓
2	To remov and replace reverse sensors	\$100.00	\$80.00	30 ✓
3	To remove and replace reverse camera	\$180.00	\$150.00	50 ✓
4	To do Argon welding on rear end panel aluminium alloy panel & etc	\$500.00	\$400.00	300
5	Labour to renew damaged rear RH door, rear end panel aluminium alloy panel & etc, and repair rear floor panel	\$1,800.00	\$1,500.00	1200 ✓
6	Spray painting on affected areas, under chassis frame & etc	\$900.00	\$600.00	300 ✓
TOTAL FOR LABOUR & SPRAY PAINTING :		\$3,630.00	\$2,830.00	

Summary

	Workshop Est. (\$)	Adjusted Cost (\$)
TOTAL FOR SPARE PARTS :	\$12,881.00	\$11,381.00
TOTAL FOR LABOUR & SPRAY PAINTING :	\$3,630.00	\$2,830.00
TOTAL REPAIR COSTS :	\$16,511.00	\$14,211.00

5 repair days

CARLINK CONSULTANCY

GBK 4606 U

Annex C: Recommendation

We have inspected thoroughly the actual damages found on the vehicle and our assessment is appended in the Annex(es) attached. The condition and age of the vehicle was considered before we reached our recommendation as to whether the parts need replacement or repair.

M/S Sin Foo Hing Battery Service estimated repair cost is **S\$16,511.00** and we have adjusted it to **S\$14,211.00** on a part by part basis. However, taking into consideration the age of the vehicle and the availability of used/recondition components. We, therefore recommend a contract lump sum repair cost.

The repairer have agreed to undertake the repairs on a contract lump sum of **S\$12,100.00**, according to acceptable quality and standard. (Repairer discretion to repair parts, to replace with old parts, or to replace with OEM or genuine parts).

The entire repair of the damaged vehicle should be completed within a reasonable period of **7** working days.

We have advised the repairer that the inspection was conducted strictly on a WITHOUT PREJUDICE basis and we have not given any instruction and authorisation to proceed with the repair of the vehicle.

We are reverting the matter to you for your discretion and enclosed is our invoice for service rendered.

Yours faithfully,
CARLINK CONSULTANCY



PATRICK NG
Automotive Engineer Assessor

MIMI, MIRTE, LCGI, I ENG, LAE, CGLI FTC.

SIN FOO HING BATTERY SERVICE

27A Jurong Port Road #01-30 Singapore 619101

Fax: 6265 8115 HP: 9733 6031

Reg. No: 52898075X

INVOICE

P.O. No.

DATE: 2 February 2021

VEH. No.: GBK 4606 U

TERMS:

M/s: Unico Total Solution Pte. Ltd.
No. 10 Fishery Port Road Singapore 619732

FINAL REPAIR BILL FOR VEHICLE NO. GBK 4606 U

Lump Sum Repairs \$12,100.00