

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

to Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

3 197/014696	EO I IIIIA I E	031 NO3			
Invoice Name & Address	Owner Name & Vehicle Info				
Tay Hee Huat	Cust No/Name Reg No/Reg Date	/Tay Hee Huat SJX9133X / 24/04/201			
Blk 234A Serangoon Avenue 2 #02-139	Date In/Mileage				
Singapore 551234		4J11XS6664			
Contact No Mobile: 90228476		MIT/OUTLANDER 2.0 2WD CVT ELEGANCE DO1 COSMIC BLUE / BK BLACK			

			- 00E	Operator	2 - 12 - 12 - 12 - 12 - 12 - 12 - 12 -	WIP No			
Account No	Terms	Date/Time Printed	CSE	Operator		11303			
CSM00041	Cash	24/05/2021/ 11:19	Bod	442 / CocoLu	Qty	Unit Price	Disc%	Ar	nount
		Description of Goods	S / Services	Company of the second s	Qty				480.00
M SUNDRY									
SUPPLY FI	RT RIGHT	TYRE						1125	3150.00
E PNT88000	,	SOULET EDT SENDED	DU FDT II	PPPORT PANEL RH, 2.5	x 450			l	
RENEW FR	T' BUMPER	, BONNET, FRI FENDER G RH, REPAIR FRT DOOF	RH. A-PI	LLAR RH	7 (10				240.00
FRT WHEEL	- HOO21M	G RH, REPAIR TRI DOOR							
E PNT88000 RENEW FR	T LITAIDSC	DEEN						1750	2100.00
			1	PII	252			1/30	_
CDDAY PA	INT FOR	FRT ¹ BUMPER, FRT ¹ FENDE	R RH, BON	NET, FRT SUPPORT RH	X 370				
FRT DOOR	RH. A-P	ILLAR, RH.		_	erent)				80.0
M CHMODY		-			15	•			
APPLY SE	ALANT FO	R FRT WINDSCREEN	91°	111/2/1/21	11/9				120.0
A LUICEL ALTC	MMENT	- 11	2011	ima'	(4)	7			20.0
To Condu	ct Comput	terize Full Wheel A	grillen C						30.0
M SUNDRY									30.0
TRANSFER	FRI KIG	11 KIM							30.0
A 54900099	STAC & EI	ECTRICAL SYSTEM							120.0
4 4000001									
TO CARRY	OUT DIAG	GNOSTIC CHECK USING H	I-SCAN PR	O TEST					
USING HI-	SCAN PRO	TEST							300.0
A 54900099									
RENEW FR	r under (CARRIAGE							40.0
M SUNDRY		A TOTAL TOTAL							20.0
	ALANT FOR	R ACCIDENT PORTION							20.0
M SUNDRY						100.00	00.00		100.0
Sundry M REFLECTOR	TATI I	AMP.LH X A/N	3		1.00		00.00		75.0
	FR RUMPFI	RRH / MIS (Black J		1.00		00.00		428.0
M GARNISH,	N.FR BUM	PER - CUT (SIVE	y '		1.00 1.00	18.00	00.00	/	18.0
M DDACKET	ED RIMPF	R STDF.RH / MIJ			1.00	48.00			48.0
M GARNISH,	FR BUMPE	R SIDE / ////	chame)		1.00	220.00	00.00	/	220.00
M CADNICH	FR RIMPF	R SIDE / OR C	(hime)			1.1			

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

GST Reg No : MR-8500111-X

ESTIMATE	and the late late
Owner	Name & Vehicle Info
Reg No/Reg Date SJX9133	/Tay Hee Huat x / 24/04/201
Chassis No GF7W0400 Engine No 4J11XS60	1404 664 LANDER 2.0 2WD CVT ELEGANCE
	Cust No/Name Reg No/Reg Date SJX91333 Date In/Mileage Chassis No GF7W0403 Engine No 4J11X566

					Onemator		WIP No		
Accou	nt No	Terms	Date/Time Printed	CSE	Operator Coccl III	1000	11303		
CSM000		Cash	24/05/2021/ 11:19	Bod	442 / CocoLu	Qty	Unit Price	Disc%	Amount
CSMCCC			Description of Good	s / Services	Section 1. Commission of the section	1.00	112.00		112.00
		D DIMPE		(home)		1.00	295.00		295.00
M GA	RNISH,	R BUMPE		_		1.00	6.00		6.00
M CO	VER, FR	BUMPER	TOT I HO DH / MI	S ,		1.00	116.00	00.00	116.00
M BR	KT, FR	SCHALEK 2	IDE, LWR RH / MI	9 42)		1.00	199.00	00.00	199.00
M MO	ULDING,	FR BUMP		(Olar)		1.00	50.00	00.00	50.00
M MO	OULDING,	FK WHEE		1		1.00	572.00	00.00	572.00
M CO	VER, HE	TOANAJUA	ATOD A DR			1.00	17.00	00.00	17.00
M GR	ILLE AS	SSY, RADIA	GRILLE RH 17 XM	M		1.00	980.00	00.00	980.00
		~ DD	GRILLE, RH 1 X X			1.00	68.00	00.00	68.00
M HO	000 /	שע י	BT X NA			_1.00 1.00	40.00	00.00	40.00
M HI	NGE, HUC	DD,RH /	N X NA	n []	J	41.00	00.00	41.00
M WE	ATHERS	TRIP, HOO	1 XM	\odot	11220 5	146.801	76.00	00.00	76.00
M WE	ATHEKS	TRIP, HOOI	XM F	≤ 111		116.65	622.00	00.00	622.00
M LA	TCH, HOC	י טע	00	R) GL		1.00	60.00	00.00	60.00
M FE	NDER, FR	R, FR FEN		4-		1.00	164.00	00.00	164.00
M IN	SULATUR	WHEELHO		1		1.00	58.00	00.00	58.00
M SH	ILELU, FR	AMD CHID	T IIPR RH][1.00	156.00	00.00	156.00
M PN	IL, MEAUL	DI AMD SI	IDPORT I WR - ~ . / .	M		1.00	60.00	00.00	60.00
M PAI	MEL, REA	SIDEMEME	SED DU ' F.MI'			1.00	113.00	00.00	113.00
M PL	AIE, FK	IIELD, FR	I LID DI	1		1.00	104.00	00.00	104.00
M FE	NUEK SI	DECK, FR	UPR RH . X /VI	ч		1.00	1530.00	00.00	1530.00
M CL	ACC LITE	DSHIELD	/ BR			2.00	92.00	00.00	184.00
n wa	HII DING	WINDSHIL	D SIDE / NC			2.00	3.00	00.00	6.00
P MO	ODDED L	INDSHIF	D GLASS			1.00	78.00	00.00	78.00
M STI	UPPER,	WINDSHI	AAA SAASSA			3.00		10 DOMEST 1	24.00
M MO	ACED UI	R WINDO	11/			1.00		00.00	54.00
M SP	D, FR FE	NOFR	A1 (1.00	92.00	00.00	92.00
M CO	VFR.FM	ROOM S	IDE, RH ? X NIN			1.00		00.00	289.00
M DA	ANEL FR	END SID				1.00		00.00	349.00
M CO	OVER.EN	G ROOM U	NDER FR - 44 'S'			1.00		00.00	173.00
M GA	ARNISH.	FR DECK	2 / 1/			1.00	19.00	00.00	19.00
M CC	OVER, FR	DECK, RH	1 XMM			1.00	544.00	00.00	544.00
M A	IR DAM,	SIDE, RH	1 XMM						

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 2 of 3



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

to Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

keg No : 197701469G	CO 1 11/11 1 1 -				
	Owner Name & Vehicle Info				
Invoice Name & Address Tay Hee Huat Blk 234A Serangoon Avenue 2 #02-139	Cilassis	/Tay Hee Huat SJX9133X / 24/04/201 / 0 GF7W0401404			
Singapore 551234 Contact No Mobile: 90228476	Make/Mode1	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE DO1 COSMIC BLUE / BK BLACK			

				Operator		WIP No		
Account No	Terms	Date/Time Printed	CSE	Operator		11303		
CSM00041	Cash	24/05/2021/ 11:19	Bod	442 / CocoLu	Qty	Unit Price	Disc%	Amount
		Description of Goods	s / Services	The second secon	1.00	190.00	00.00	190.00
M GARNISH,	FR DOOR				1.00	2135.00	00.00	2135.00
M HEADLAMP	ASSY RH	- 00			1.00	348.00	00.00	348.00
M LAMP ASS'	Y.FOG.FR	DU / (AI			1.00	87.00	00.00	87.00
M TANK WIN	DSHIELD !	WASHER / CAM			1.00	5.00	00.00	5.00
M GROMMET.	WINDSHIE	LD WASHER	1// 1		1.00	23.00	00.00	23.00
M HOSE W/SI	HLD WSHR	TANK FLR	MM		1.00	156.00	00.00	156.00
M MOTOR.WI	NDSHIELD	WASHER(*)	ММ		1.00	114.00	00.00	114.00
M SENSOR.W.	/SHLD WAS	SHER TANK	164		1.00	861.00	00.00	861.00
M CONDENSE	R ASSY, A	/C REFRIGE . ~ ~ /			1.00	191.00	00.00	191.00
M HOSE A/C	COMPR D	ISCHARGE - X /		1	1.00	262.00	00.00	262.00
M PIPE.A/C	CONDENS	ER OUTLE!	以 几日		7 5 3.00		00.00	235.00
M HOSE A/C	COMPR SI	UCTION 1/2/3	277	Inniz	1.00	1291.00	00.00	1291.00
M SHAFT AS	FR AXLE	DRIVE, RH	3011	111111(0	4.00	7 1067.00	00.00	1067.0
M CROSSMEM	BER, FR A	XLE, NO.1			1.00	325.00	00.00	325.0
M ARM ASSY.	FR SUSP	,LWR RH _ · / / /	l)		1.00	469.00	00.00	469.0
STRUT.FR	SUSP, RH	/ 101			1.00	32.00	00.00	32.0
M REARING.	R SUSP S	STRUT - IFC	v i		1.00	1223.00	00.00	1223.0
M GEAR & L	INK ASSY	STEERING "			1.00	63.00	00.00	63.0
M END ASSY,	TIE ROD	E1 / 19101			1.00	863.0	00.00	863.0
M FACE.FR	BUMPER	_ OX			1.00	26.0	00.00	/ 26.0
M BRACKET,	IU ADHES	SIVE / NC		-1 CIV	11 00	11. 1	, 1	
				Steve CLK 24/8/21, 3.90	K) U	- MA A		
				24/5/11, 300	opm Ex	ress-		
				7.11	ρ	P, My days	BAL S	1
						, ,		J
Γ	LKK Aut	o Consultants hence notify			/1	das		
	the Ren	airer of the following:				V.		
1	. To resur	vev before/after spray painting	The same			•		
1	. To displ	av damaged part(s) during resurve	еу			4		
1	• Parts pr	rices are subject to confirmation	nce' besis					
Confirm &	accepted:	by nodrication(s) is allowed						04.016
300 10		mentary (tom (s) must be resurvey	ed and				ett	24,816.
	is subje	ect to final epproval from Insurance	a Company		7% GST o	n 24816	.00	1737.
		Land by Spice ref						26 553
8	1	ledged by Riepairer	and the state of t			Total Paya	ble	26,553.
İ	Signatur	er,						
4	1 1 1 1 1	ry and company stamp						

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 3 of 3