



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



### ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Tay Hee Huat	Cust No/Name /Tay Hee Huat
B1k 234A Serangoon Avenue 2	Reg No/Reg Date SJX9133X / 24/04/201
#02-139	Date In/Mileage / 0
Singapore 551234	Chassis No GF7W0401404
Contact No Mobile: 90228476	Engine No 4J11XS6664
	Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE
	Colour/Trim D01 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	24/05/2021/ 11:19	Bod	442 / CocoLu	11303			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								480.00
SUPPLY FRT RIGHT TYRE								
E PNT88000								3150.00
RENEW FRT BUMPER, BONNET, FRT FENDER RH, FRT UPPPORT PANEL RH,								
FRT WHEEL HOUSING RH, REPAIR FRT DOOR RH, A-PILLAR RH								
E PNT88000								240.00
RENEW FRT WINDSCREEN								
E PNT98000								2100.00
SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH, BONNET, FRT SUPPORT RH								
FRT DOOR RH, A-PILLAR RH.								
M SUNDRY								80.00
APPLY SEALANT FOR FRT WINDSCREEN.								
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								30.00
TRANSFER FRT RIGHT RIM								
A 54900099								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
A 54900099								300.00
RENEW FRT UNDER CARRIAGE								
M SUNDRY								40.00
APPLY SEALANT FOR ACCIDENT PORTION								
M SUNDRY								20.00
Sundry								
M REFLECTOR, TAIL LAMP, LH					1.00	100.00	00.00	100.00
M GARNISH, FR BUMPER, RH					1.00	75.00	00.00	75.00
M EXTENSION, FR BUMPER					1.00	428.00	00.00	428.00
M BRACKET, FR BUMPER SIDE, RH					1.00	18.00	00.00	18.00
M GARNISH, FR BUMPER SIDE					1.00	48.00	00.00	48.00
M GARNISH, FR BUMPER SIDE					1.00	220.00	00.00	220.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Tay Hee Huat	Cust No/Name	/Tay Hee Huat
B1k 234A Serangoon Avenue 2	Reg No/Reg Date	SJX9133X / 24/04/201
#02-139	Date In/Mileage	/ 0
Singapore 551234	Chassis No	GF7W0401404
Contact No Mobile: 90228476	Engine No	4J11XS6664
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE
	Colour/Trim	DO1 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	24/05/2021/ 11:19	Bod	442 / CocoLu	11303			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	GARNISH,FR BUMPER SIDE				1.00	112.00	00.00	112.00
M	COVER,FR BUMPER				1.00	295.00	00.00	295.00
M	BRKT,FR BUMPER SIDE,LWR RH				1.00	6.00	00.00	6.00
M	MOULDING,FR BUMPER,RH				1.00	116.00	00.00	116.00
M	MOULDING,FR WHEEL ARCH,RH				1.00	199.00	00.00	199.00
M	COVER,HEADLAMP SUPT PANEL				1.00	50.00	00.00	50.00
M	GRILLE ASSY,RADIATOR				1.00	572.00	00.00	572.00
M	BRACKET,RADIATOR GRILLE,RH				1.00	17.00	00.00	17.00
M	HOOD				1.00	980.00	00.00	980.00
M	HINGE,HOOD,RH				1.00	68.00	00.00	68.00
M	WEATHERSTRIP,HOOD				1.00	40.00	00.00	40.00
M	WEATHERSTRIP,HOOD				1.00	41.00	00.00	41.00
M	LATCH,HOOD				1.00	76.00	00.00	76.00
M	FENDER,FR RH				1.00	622.00	00.00	622.00
M	INSULATOR,FR FENDER,RH				1.00	60.00	00.00	60.00
M	SHIELD,FR WHEELHOUSE,RH				1.00	164.00	00.00	164.00
M	PNL,HEADLAMP SUPT,UPR RH				1.00	58.00	00.00	58.00
M	PANEL,HEADLAMP SUPPORT,LWR				1.00	156.00	00.00	156.00
M	PLATE,FR SIDEMEMBER,RH				1.00	60.00	00.00	60.00
M	FENDER SHIELD,FR LWR RH				1.00	113.00	00.00	113.00
M	FRAME,FR DECK,FR UPR RH				1.00	104.00	00.00	104.00
M	GLASS,WINDSHIELD				1.00	1530.00	00.00	1530.00
P	MOULDING,WINDSHILD SIDE				2.00	92.00	00.00	184.00
M	STOPPER,WINDSHIELD GLASS				2.00	3.00	00.00	6.00
M	MOULDING,WINDSHIELD				1.00	78.00	00.00	78.00
M	SPACER,QTR WINDOW				3.00	8.00	00.00	24.00
M	PAD,FR FENDER				1.00	54.00	00.00	54.00
M	COVER,ENG ROOM SIDE,RH				1.00	92.00	00.00	92.00
M	PANEL,FR END SIDE,RH				1.00	289.00	00.00	289.00
M	COVER,ENG ROOM UNDER,FR				1.00	349.00	00.00	349.00
M	GARNISH,FR DECK				1.00	173.00	00.00	173.00
M	COVER,FR DECK,RH				1.00	19.00	00.00	19.00
M	AIR DAM,SIDE,RH				1.00	544.00	00.00	544.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Tay Hee Huat	Cust No/Name /Tay Hee Huat
B1k 234A Serangoon Avenue 2	Reg No/Reg Date SJX9133X / 24/04/201
#02-139	Date In/Mileage / 0
Singapore 551234	Chassis No GF7W0401404
Contact No Mobile: 90228476	Engine No 4J11XS6664
	Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE
	Colour/Trim D01 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	24/05/2021/ 11:19	Bod	442 / CocoLu	11303		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	GARNISH,FR DOOR,RH			1.00	190.00	00.00	190.00
M	HEADLAMP ASSY,RH			1.00	2135.00	00.00	2135.00
M	LAMP ASSY,FOG,FR RH			1.00	348.00	00.00	348.00
M	TANK,WINDSHIELD WASHER			1.00	87.00	00.00	87.00
M	GROMMET,WINDSHIELD WASHER			1.00	5.00	00.00	5.00
M	HOSE,W/SHLD WSHR TANK FLR			1.00	23.00	00.00	23.00
M	MOTOR,WINDSHIELD WASHER(*)			1.00	156.00	00.00	156.00
M	SENSOR,W/SHLD WASHER TANK			1.00	114.00	00.00	114.00
M	CONDENSER ASSY,A/C REFRIGE			1.00	861.00	00.00	861.00
M	HOSE,A/C COMPR DISCHARGE			1.00	191.00	00.00	191.00
M	PIPE,A/C CONDENSER OUTLET			1.00	262.00	00.00	262.00
M	HOSE,A/C COMPR SUCTION			1.00	235.00	00.00	235.00
M	SHAFT AS,FR AXLE DRIVE,RH			1.00	1291.00	00.00	1291.00
M	CROSSMEMBER,FR AXLE,NO.1			1.00	1067.00	00.00	1067.00
M	ARM ASSY,FR SUSP,LWR RH			1.00	325.00	00.00	325.00
M	STRUT,FR SUSP,RH			1.00	469.00	00.00	469.00
M	BEARING,FR SUSP STRUT			1.00	32.00	00.00	32.00
M	GEAR & LINK ASSY,STEERING			1.00	1223.00	00.00	1223.00
M	END ASSY,TIE ROD			1.00	63.00	00.00	63.00
M	FACE,FR BUMPER			1.00	863.00	00.00	863.00
M	BRACKET, IU ADHESIVE			1.00	26.00	00.00	26.00

Confirm &amp; accepted by

**Nett** 24,816.00  
**7% GST on** 24816.00 1737.12  
**Total Payable** 26,553.12

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.