



# RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd  
Blk 8 , Kaki Bukit Avenue 4 , #02-24  
Premier @ Kaki Bukit Singapore 415875  
Email: claims@rico60.com  
Tel: 6286 6060 Fax : 6286 7060

## RICO Office Use Only

Parts -5%	
SN	
Labour	
Total	
Lump Sum	
ERV	40K

TO: ETIQA

Vehicle No : SMK 5052 E

Make & Model : BMW 428i

DATE: 18/5/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	TAILGATE	1	\$ 1,267.50	\$ <del>bt</del> 1,267.50
2	TAILGATE LOGO	1	\$ 125.00	\$ <del>nei</del> 125.00
3	TAILGATE WINDSCREEN MOULDING	1	\$ 198.00	\$ <del>nei</del> 198.00
4	TAILGATE WINDSCREEN INNER SEAL	1	\$ 50.00	\$ <del>nei</del> 50.00
5	TAILGATE EMBLEM(428i)	1	\$ 89.00	\$ <del>nei</del> 89.00
6	TAILGATE NUMBER PLATE LAMP	2	\$ 89.00	\$ <del>x</del> 178.00
7	TAILGATE OPENER SWICTH	1	\$ 217.90	\$ <del>x</del> 217.90
8	TAILGATE LAMP	2	\$ 565.00	\$ <del>x</del> 1,130.00
9	TAILGATE STOPPER	2	\$ 25.00	\$ <del>x</del> 50.00
10	TAILGATE INNER TRIM <i>plus fo</i>	1	\$ 525.00	\$ <del>?</del> 525.00
11	TAILGATE BOTTOM LOCK	1	\$ 665.00	\$ <del>?</del> 665.00
12	TAILGATE TOP LOCK CATCH	1	\$ 46.00	\$ <del>x</del> 46.00
13	TAILGATE WEATHERSTRIP	1	\$ 298.40	\$ <del>not</del> 298.40
14	TAILGATE LOCK DETECTOR	1	\$ 317.90	\$ <del>nei</del> 317.90
15	TAIL GATE FLOOR SCAN SENSOR SUPPORT	1	\$ 189.00	\$ <del>nei</del> 189.00
16	TAIL GATE FLOOR SCAN SENSOR 1	1	\$ 265.00	\$ <del>nei</del> 265.00
17	TAIL GATE FLOOR SCAN SENSOR 2	1	\$ 265.00	\$ <del>nei</del> 265.00
18	TAIL GATE FLOOR SCAN SENSOR UNIT	1	\$ 387.00	\$ <del>dis</del> 387.00 ✓
19	TAIL LAMP	2	\$ 526.10	\$ <del>nei</del> 1,052.20
20	TAIL LAMP SIDE GARNISH	2	\$ 189.00	\$ <del>dei</del> 378.00
21	REVERSE CAMERA	1	\$ 1,256.00	\$ <del>x</del> 1,256.00
22	REAR BUMPER	1	\$ 1,220.30	\$ <del>dei</del> 1,220.30
23	RAER BUMPER CHROME MOULDING	1	\$ 332.00	\$ <del>out</del> 332.00
24	REAR BUMPER TOP GARNISH	1	\$ 253.00	\$ <del>dei</del> 253.00
25	REAR BUMPER SIDE RETAINER	2	\$ 254.00	\$ <del>nei</del> 508.00
26	REAR BUMPER SIDE GARNISH <i>RHX LH-m</i>	2	\$ 255.50	\$ <del>x</del> 511.00



27	REAR BUMPER REINFORCEMENT	1	\$	570.90	\$ <del>66</del> 570.90
28	REAR BUMPER CENTER RETAINER	1	\$	377.50	\$ <del>am</del> 377.50
29	REAR BUMPER REFLECTOR	2	\$	177.90	\$ <del>am</del> 355.80
30	REAR BUMPER TOW COVER	1	\$	56.00	\$ <del>x</del> 56.00
31	REAR BUMPER UNDER SIDE COVER	1	\$	211.50	\$ <del>de</del> 211.50
32	REVERSE SENSOR	2 <del>4</del>	\$	378.90	\$ <del>sm</del> 1,515.60
33	REVERSE SENSOR HOLDER	4	\$	35.00	\$ <del>net</del> 140.00
34	REVERSE SENSOR WIRIHARNESS	1	\$	899.00	\$ <del>x</del> 899.00
35	END PANEL	1	\$	758.00	\$ <del>bt</del> 758.00
36	END PANEL TOP TRIM	1	\$	288.70	\$ <del>de</del> 288.70
37	REAR FLOOR PANEL	1	\$	973.40	\$ <del>x</del> 973.40
38	REAR FLOOR PANEL TOP BOARD	1	\$	652.00	\$ <del>de</del> 652.00
39	REAR FLOOR PANEL TOOL BOARD	1	\$	317.40	\$ <del>x</del> 317.40
40	REAR FENDER INNER TRIM	2	\$	470.00	\$ <del>x</del> 940.00
41	REAR FENDER INNER SHIELD	2	\$	198.70	\$ <del>x</del> 397.40
42	REAR EXHAUST SILENSER <i>photo</i>	1	\$	1,230.40	\$ <del>?</del> 1,230.40
43	REAR EXHAUST MOUNTING	2	\$	50.00	\$ <del>x</del> 100.00
44	REAR EXHAUST GASKET	1	\$	45.00	\$ <del>x</del> 45.00
45	REAR EXHAUST HEAT PLATE CENTER	1	\$	217.00	\$ <del>66</del> 217.00
46	REAR EXHAUST HEAT PLATE SIDE	1	\$	156.00	\$ <del>66</del> 156.00
47	FRONT DRIVER SEAT BELT <i>photo</i>	1	\$	689.00	\$ <del>?</del> 689.00
48	FRONT DRIVER SEAT BELT BARKER	1	\$	854.00	\$ <del>?</del> 854.00
49	SRS COUNTOR UNIT	1	\$	1,542.00	\$ <del>?</del> 1,542.00
50	FRONT DOOR PILLER INNER TRIM RH	1	\$	685.00	\$ <del>x</del> 685.00
51	FRONT DOOR STEP GARNISH	1	\$	189.00	\$ <del>x</del> 189.00

Subtotal : \$ 25,934.80

Less 5% \$ 1,296.74

Parts Total : \$ 24,638.06

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ <del>40</del> 80.00
2	REAR WINDSCREEN INNER SEAL	1	\$ 80.00	\$ <del>40</del> 80.00
3	TAILGATE INNER TRIM CLIP	1	\$ 40.00	\$ <del>20</del> 40.00
4	TAIL LAMP SIDE GARNISH CLIPS	1	\$ 50.00	\$ <del>x</del> 50.00
5	REAR BUMPER CLIP	1	\$ 50.00	\$ <del>30</del> 50.00
6	REAR BUMPER UNDER COVER CLIP	1	\$ 40.00	\$ <del>10</del> 40.00
7	END PANEL SEALANT	1	\$ 80.00	\$ <del>40</del> 80.00
8	END PANEL TOP TRIM CLIP	1	\$ 30.00	\$ <del>10</del> 30.00
9	REAR FLOOR PANEL SEALANT	1	\$ 80.00	\$ <del>x</del> 80.00
10	REAR FENDER INNER TRIM CLIP	1	\$ 50.00	\$ <del>x</del> 50.00

11	REAR FENDER INNER SHIELD CLIP	1	\$	40.00	\$	X	40.00
13	FRONT DOOR PILLER INNER TRIM CLIPS	1	\$	60.00	\$	X	60.00
					\$		680.00
<b>LABOUR (REAR)</b>						<b>PRICE</b>	
PANEL BEATING, REMOVAL AND REPLACING PARTS				700	\$		1,600.00
TO SPRAY PAINT AFFECTED AREA				800	\$		1,600.00
TO PERFORM LIGHTING & WIRING CHECK					\$	30	150.00
TO APPLY ANTI-RUST & TUFF KOTE					\$	30	150.00
REMOVE AND INSTALL REAR WINDSCREEN					\$	100	150.00
REMOVE AND INSTALL TAIL GATE MECHANISIM AND PART					\$	60	150.00
REMOVE INSTALL AND CHECK REVERSE CAMARA					\$	30	200.00
REMOVE INSTALL AND CHECK REVERSE SENSOR					\$	30	200.00
REMOVE AND INSTALL CARPET,TRIM AND INTERRIOR					\$	60	400.00
REMOVE AND INSTALL REAR EXHAUST					\$	60	150.00
RESET SRS SYSTEM					\$	180	350.00
<b>LABOUR TOTAL</b>						\$	5,100.00
					<b>Total Parts Cost</b>	\$	25,318.06
					<b>Total Labour Cost</b>	\$	5,100.00
					<b>Total Repair Cost</b>	\$	30,418.06

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Tanpin 97495749  
WP' 24/8/71 @ 3pm  
1/5 Resing after repair  
tanpin @ 1hr 45 min  
6 days

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	408D
<b>Vehicle Details</b>	
Vehicle No.:	SMK5052E
Vehicle to be Exported:	No
Intended Deregistration Date:	18 May 2021
Vehicle Make:	B.M.W.
Vehicle Model:	428i GRAN COUPE A/T SR HID NAV HUD
Primary Colour:	Brown
Manufacturing Year:	2014
Engine No.:	B4690967N20B20A
Chassis No.:	WBA4A52080GA69342
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$47,400.00
Original Registration Date:	13 Mar 2015
First Registration Date:	13 Mar 2015
Transfer Count:	2
Actual ARF Paid:	\$53,360.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Mar 2025
PARF Rebate Amount:	\$34,684.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	12 Mar 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$68,668.00
COE Rebate Amount:	\$26,176.00
<b>Total Rebate Amount:</b>	<b>\$60,860.00</b>

The information contained herein is correct as at 18 May 2021

OK



Date of Accident : 17/5/2021 Accident Time: 1540 (24-HR-Format)  
Accident Place : Serangoon North Ave 6  
Vehicle No. (Car Plate No.) : SMK 5052E Make/Model: BMW 428iC  
Insurance Company : FWD Policy No: PNPV2019-00009604-01  
Owner or Company Name /IC No. : Poh Bi Juan (S8634408D)  
Owner or Company Contact No. : 9109 3412 Owner's Hp \_\_\_\_\_ Company Tel \_\_\_\_\_  
DRIVER'S Name / IC No. : Tong Wei Hong (S8040070E)  
DRIVER'S Date Of Birth : 17/12/1980 DRIVER'S License Pass Date 08/05/2007  
Relationship of Owner & Driver : ☒ Spouse \ ☐ Parents \ ☐ Children \ ☐ Sibling \ ☐ Employee \ ☐ Others: \_\_\_\_\_  
DRIVER'S Address : Blk 314B Punggol Way #12-623 S(822314)  
DRIVER'S Contact No./ Alt No. : 1) 9431 3856 2) \_\_\_\_\_  
DRIVER'S Occupation : ☒ INDOOR \ ☐ OUTDOOR (e.g. working inside or outside office)  
Email Address : thomas.york25@yahoo.com.sg  
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ ☒ AFTER RAIN & WET  
Reporting Type : Reporting Only \ Claim ☒ Other Party \ Claim Own Insurance  
Number of Passengers (Including Driver): 1  
Was the accident reported to the police? YES ☒ NO  
Was there any video Captured by car camera: YES \ ☒ NO  
Exact purpose for which vehicle was being used at the time of accident: Private use \ ☒ Work purpose  
Any Injury (If YES, Pls state): YES, Driver

**Other Party Driver's Particular (if any)**

Vehicle No: SML 4912 A  
Vehicle Make/Model: \_\_\_\_\_  
Name Driver: \_\_\_\_\_  
IC No. Driver/Contact: \_\_\_\_\_

Vehicle No: \_\_\_\_\_  
Vehicle Make/Model: \_\_\_\_\_  
Name Driver: \_\_\_\_\_  
IC No. Driver/Contact: \_\_\_\_\_

**\* NEW - Passenger's name & gender:**

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### **8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


*Poh Si Juan*

Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### **Sketch Plan**

Vehicle A: SMK 5052 E	
Vehicle B: SML 4912 A	

**Describe Circumstances of the Accident**

On the stated date and time, I vehicle A was stationary on the stated venue. Suddenly, I felt a huge impact on the rear of my vehicle. I then came down to check and realised that it was vehicle B who have collided onto my vehicle.

**Declaration**

We declare the foregoing particulars are true in every respect.

Poh Bi Juan

Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel