



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08818/TAN GUO HUI (CHEN GUOHUI) Reg No/Reg Date SMJ5537D*KC17/ 12/03/201 Date In/Mileage 24/05/2021/ 42549 Chassis No KNAF3416MK5030189 Engine No G4FGJH719421 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	24/05/2021/ 11:24	QUK	289 / Patrick Lee KEVIN	33742

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER				400.00
E PNT98000 SPRAY PAINT WORK ON FRT BUMPER AND AFFECTED AREAS				350.00
E PNT88000 TO REMOVE AND INSTALL FRT PARKING ASSIST SENSOR				80.00
A 54900099 CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY TO SUPPLY FRT NUMBER PLATE WITH FRAME				50.00
M SUNDRY SUNDRIES				24 50.00
M COVER-FR BUMPER / DD ? - BR	1.00	633.00	20.00	506.40
M GRILLE ASSY-RADIATOR ? - BR	1.00	328.00	20.00	262.40
M GARNISH-RADIATOR GRILLE ? - BR	1.00	38.00	20.00	30.40
M GRILLE-FRONT BUMPER ? CUT (Black)	1.00	485.00	20.00	388.00
M MOULDING-FRONT BUMPER, RH ? X N/A	1.00	216.00	20.00	172.80
M ABSORBER-FRONT BUMPER ENERGY ? - BR	1.00	84.00	20.00	67.20
M ORNAMENT-KIA NO.115 NPC	1.00	32.00	20.00	25.60
M LAMP ASSY-HEAD, RH ? X N/A	1.00	2210.00	20.00	1768.00
M COVER-FR BUMPER FOG LAMP, RH X N/A	1.00	15.00	20.00	12.00

Estimate

SURVEYOR NAME: Steve CLKK 24/5/21, 1-35pm

SURVEYOR SIGNATURE: DD-N/A AL

DATE: Expire - ?

REMARKS: PIP, R, Bel SK

Confirm & accepted by  
Link Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
Authorized signatory and company stamp

3 dys

Nett 4,312.80  
7% GST on 4312.80 301.90  
Total Payable 4,614.70

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.