



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21006079/Auf3e2	
			Date: 14/09/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 1706K	Veh. Inspected	FBQ 8496L
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/05/21/2031	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	24/05/2021
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA AEROX	c.c	155
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MH3SG4640KJ062799	Colour	BLUE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	110/80 R14	PIRELLI	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	140/70 R14	PIRELLI	6 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/05/2021	Inspection Date	25/05/2021
	Survey held at	FIRST MOTOR BLK 3006 UBI RD 1 #01-398 SINGAPORE 408700		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	