



CLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Hoon Aik Seong Reg No/Reg Date SKW7691H / 16/11/201 Date In/Mileage / 0 Chassis No KNAFZ411MF5472112 Engine No G4FGFH784982 Make/Model KIA/FORTE K3 1.6 A SX AAC PREMIUM Colour/Trim K3R / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	24/05/2021/ 13:01	BLE	261 / Edwin Caina	33752			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								880 1600.00
RENEW RHR ¹ DOOR PNL & RH ROCKER PNL BODY KIT					2 days + 80			
REPAIR RHR ¹ FENDER & RH ROCKER PNL								1350 1400.00
E PNT98000								
RESPRAY RHR ¹ DOOR , RHR ¹ FENDER , RH ROCKER PNL & RH ROCKER PNL BODY KIT					3 x 350			120.00
E PNT88000								120.00
REMOVE & REFIT RHR DOOR COMPONENT								120.00
E PNT88000								30.00
REMOVE & REFIT TRIM & REAR SEAT TO FACILITATE REPAIR								120.00
A 54900099								40.00
CHECK WIRING ELECTRICAL SYSTEM								40.00
A 10028901								20.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								40.00
USING HI-SCAN PRO TEST								40.00
M SUNDRY								20.00
APPLY ANTI CORROSION ON AFFECTED AREAS								1088.80
M SUNDRY								71.20
SUPPLY BODY PNL SEALANT								6.40
M SUNDRY								8.80
Sundries					1.00	1361.00	20.00	21.60
M PANEL ASSY-REAR DOOR,RH					1.00	89.00	20.00	46.40
M W/STRIP ASSY-RR DR BELT O/S RH					1.00	8.00	20.00	17.60
M TAPE-RR DR FRAME BLACK RR,RH					1.00	11.00	20.00	1000.00
M BLACK TAPE-RR DR FRAME UPR,RH					1.00	27.00	20.00	
M FILM-ANTI CHIPPG RH					1.00	58.00	20.00	
M HANDLE ASSY-DOOR OUTSIDE					1.00	22.00	20.00	
M COVER-FR DR O/S HDL,PASSENGER					1.00	1000.00	00.00	
M K3 TEMPTATION RED K3R								

Estimate

SURVEYOR NAME : Steve CLKK

24/5/21, 4:00pm

SURVEYOR NAME : Steve CLKK 24/5/21, 4.00pm

SURVEYOR SIGNATURE : OD-AL AL

Confirm & accepted by

DATE : EXPRS - 1

7% GST on 5,750.80 402.56
Total Payable 6,153.36

REMARKS : PIP, R, Bel 21

4 days

Authorized signatory and company stamp

Auto Consultants hence notify
Repairer of the following:
resurvey before/after spray painting
display damaged part(s) during resurvey
parts prices are subject to confirmation
third party survey is on a "without prejudice" basis
this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include
any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered
after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a
deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or
cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing
the rubber seal or other repair requiring the removal of the windscreen.