

SIN BOON MOTOR CO
10 ADMIRALTY STREET,
#01-10/11, NORTHLINK BUILDING,
SINGAPORE 757695
TEL: 6257 8404, FAX: 6755 6214

DATE: 20/05/2021

FR7889R - KAWASAKI EX400R
VEHICLE REPAIR QUOTATION

HK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer

Signature:

Date:

1	1 PC TOP WINDSHIELD	cut	\$275.00	128
2	1 PC L/H MIRROR	cut	\$225.00	129
3	1 PC R/H MIRROR	cut	\$225.00	129
4	1 PC TOP COWLING	BR	\$975.00	190
5	1 PC L/H SIGNAL FENDER FRONT	cut	\$80.00	✓
6	1 PC L/H SIDE FENDER UPPER	cut	\$630.00	✓
7	1 PC L/H LOW COWLING	cut	\$340.00	255
8	1 PC HEADLIGHT (LED)	CRA	\$2,410.00	755
9	LAMPSTAY (BRACKET)	BT	\$478.00	75
10	R/H SIGNAL FENDER	re	\$82.00	✓
11	R/H SIDE FENDER REAR	x repair	\$215.00	X
12	R/H LOWER COWLING	re	\$328.00	255
13	R/H HANDLE BAR	BT	\$242.00	185
14	L/H FORK	BT	\$1,440.00	880
15	R/H FORK	BT	\$1,440.00	880
16	FORK LOWER BRACKET	BT	\$605.00	✓
17	FORK UPPER BRACKET	BT	\$595.00	545
18	FUEL TANK (PETROL)	DD	\$1,920.00	880
19	L/H TAIL FENDER	cut	\$156.00	✓
20	R/H TAIL FENDER	cut	\$156.00	✓
21	EXHAUST PROTECTOR (MUFFLER)	cut	\$456.00	160
22	FRONT FENDER (MAGUARD)	CRA	\$380.00	288
23	L/H FRAME SLIDER	cut	\$80.00	40
24	R/H FRAME SLIDER	cut	\$80.00	40
25	L/H HANDLE BAR END PLUG	cut	\$80.00	35
26	FRONT RIM SHAFT	BT	\$153.00	97
27	L/H FOOT REST FRONT	NN	\$136.00	X
28	STEERING CONE BEARING	ML	\$210.00	82.78
29	FRONT RIM	BT	1250	850
			\$14,392.00	
			LESS 10%	\$1,439.20
				\$12,952.80 7729.00

29	FRONT NUMBER PLATE	ML	NETT	\$20.00	10
30	LABOUR		NETT	\$600.00	350
31	TOW		NETT	\$60.00	50
				\$13,632.80	410
			GST 7%	\$954.30	
				\$14,587.10	
				8139.00	

4 Days
Lumpsum repair
After repair photos.
Guo Qiang - 82880282
Guo Qiang@hkauto.com
24/5/21