



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 2487P

| Qty                | Description of Parts  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--------------------|---|----------------------|---------------------------|-------------------|
|                    | <b><u>REPLACEMENT OF PARTS</u></b>  |                      |                           |                   |
| 1                  | LHS FRONT DOOR (CONSISTENT)   | TO REPAIR SEE LABOUR | 1,184.35                  | -                 |
| 1                  | LHS FRONT DOOR LOWER MOULDING (CONSISTENT)  | NOT NECESSARY        | 178.00                    | -                 |
| 1                  | LHS FRONT DOOR UPPER MOULDING (CONSISTENT)  | NOT NECESSARY        | 192.00                    | -                 |
| 1                  | LHS FRONT CHROME GARNISH (CONSISTENT)   | NOT NECESSARY        | 122.00                    | -                 |
| 1                  | LHS REAR SLIDING DOOR (CONSISTENT)  | TO REPAIR SEE LABOUR | 1,556.00                  | -                 |
| 1                  | LHS REAR SLIDING DOOR UPPER MOULDING (CONSISTENT)   | NOT NECESSARY        | 178.00                    | -                 |
| 1                  | LHS REAR SLIDING DOOR LOWER MOULDING (CONSISTENT)   | NOT NECESSARY        | 192.00                    | -                 |
| 1                  | LHS REAR SLIDING DOOR CHROME GARNISH (CONSISTENT)   | NOT NECESSARY        | 128.00                    | -                 |
|                    | LESS 25% DISCOUNT   |                      | -932.59                   | -                 |
|                    |   |                      | 2,797.76                  | -                 |
|                    | <b><u>LABOUR</u></b>  |                      |                           |                   |
|                    | TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS.INCLUSIVE OF THE REPAIR OF LHS FRONT DOOR AND LHS REAR SLIDING DOOR . |                      | 800.00                    | 300.00            |
|                    | TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED.  |                      | 600.00                    | 500.00            |
|                    | TO REMOVE,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION .   | NOT NECESSARY        | 200.00                    | -                 |
|                    | TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS .  |                      | 240.00                    | 30.00             |
|                    |   |                      | 1,840.00                  | 830.00            |
| <b>GRAND TOTAL</b> |   |                      | <b>4,637.76</b>           | <b>830.00</b>     |

|                                    |  |  |               |
|------------------------------------|--|--|---------------|
| <b>RECOMMENDED COST OF REPAIRS</b> |  |  | <b>830.00</b> |
|------------------------------------|--|--|---------------|

Report Ref No. CC4/ASM21006092/Trs3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.