



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN			Ref: CC4/ASM21006092/Trs3q2 Date: 17/02/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3617K	Veh. Inspected	SKD 2487P	
Policy No.	P2419138	Coverage (\$)	0.00	
Claim No.	S1M038RK	Excess (\$)	0.00	
Assign From		Assign Date	24/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA AERAS	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	ACR507106910	Colour	BLACK	
Odometer	175007 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	FIRENZA	6 mm	
L/H Front Tyre	225/50 R17	FIRENZA	6 mm	
R/H Rear Tyre	225/50 R17	FIRENZA	6 mm	
L/H Rear Tyre	225/50 R17	FIRENZA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/04/2021	Inspection Date	24/05/2021	
Survey held at	ECO AUTOMOBILE CLAIMS & REPAIR PTE LTD 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417808			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	