

REPAIR ESTIMATE*

VEHICLE NO SHC7668S

DATE 22/05/2021

MAKE :

MODEL : HYUNDAI IONIQ

/ CHIANG ~~ATTC~~ AICg

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	REAR DOOR OUTER MOULDING LH			\$125.30	X SUC
1	REAR LH DOOR PANEL			\$1,789.90	XR
1	REAR ROCKER GARNISH LH			\$715.60	XR
1	REAR WHEEL COVER LH			\$346.40	/ SCR
	SUB TOTAL			\$2,977.20	
	LESS 20%			\$595.44	
	DISCOUNTED TOTAL			\$2,381.76	
1	PETROL STICKER			\$10.00	/ NEC
1	REAR DOOR COMFORT APP STICKER			\$80.00	/ NEC
				\$90.00	
	Labour Charge				
	Panel Beating			\$1,050.00	/
	Spray Painting Charge			\$1,000.00	850
	Remove/refix door parts			\$120.00	X NN
	Remove/Refix rear upholstery			\$90.00	X NN
	Tuff coating			\$90.00	40
	Check Wiring			\$60.00	X NN
	TOTAL LABOUR			\$2,410.00	
				\$4,881.76	
	ESTIMATE TOTAL			\$4,881.76	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

NA2 CLK
 24/5/2021 1600
 PIP
 3 DAYS
 AFTER REPAIR PHOTOS