

Our Job Ref No : 305470115

Date : 06/01/21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SHC7668S

22/05/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

2 The repair job shall bill to: AIG SKE815J

2. The finalized amount shall be:

(a) Spare Parts after List discount \$367.12

(b) Labour Charges \$1,940.00

Total for Part-By-Part Repair Cost \$2,307.12

(c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : CHIANG

Name : NAZ LKK

Tel : 62148314

Date : 2/6/2021

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

AAZ-1 B16

COMFORTDELGRO ENGINEERING PTE LTD

Date: 01.06.2021

REPAIR ESTIMATE

Time: 14:00:28

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305470115
REGN NO : SHC7668S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 11.11.2019
DATE/TIME IN : 22.05.2021 10:25
ACCIDENT DATE : 22.05.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 28-01-0302-2018-A	FUEL TANK LID (PETROL ONL	1	10.00	0.00	10.00	✓ NEL
0002 28-01-9999-2024-A	APP LOGO REAR DOOR L/R CC	1	80.00	0.00	80.00	✓ NEL
0003 03-01-0104-2137-G	CAP ASSY-WHEEL HUB	1	346.40	20.00	277.12	✓ SCR

SUB-TOTAL : 367.12

JOB NATURE

0000 PB	PANEL BEATING	1050.00	✓
0001 SP	SPRAYPAINT CHARGE	850.00	✓
0002 20-00	TUFF COAT ON AFFECTED PARTS.	40.00	✓

SUB-TOTAL : 1,940.00

TOTAL : 2,307.12

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

REPAIR ESTIMATE*

VEHICLE NO SHC7668S

DATE 22/05/2021

MAKE :

MODEL : HYUNDAI IONIQ

/ CHIANG ~~ATUC~~ AICg

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	REAR DOOR OUTER MOULDING LH			\$125.30	X SUC
1	REAR LH DOOR PANEL			\$1,789.90	X R
1	REAR ROCKER GARNISH LH			\$715.60	X R
1	REAR WHEEL COVER LH			\$346.40	X SCR
	SUB TOTAL			\$2,977.20	
	LESS 20%			\$595.44	
	DISCOUNTED TOTAL		277.12	\$2,381.76	
1	PETROL STICKER			\$10.00	X NEC
1	REAR DOOR COMFORT APP STICKER			\$80.00	X NEC
				\$90.00	
	Labour Charge				
	Panel Beating			\$1,050.00	/
	Spray Painting Charge			\$1,000.00	850
	Remove/refix door parts			\$120.00	X NN
	Remove/Refix rear upholstery			\$90.00	X NN
	Tuff coating			\$90.00	40
	Check Wiring			\$60.00	X NN
	TOTAL LABOUR			\$2,410.00	
				\$4,881.76	
	ESTIMATE TOTAL			\$4,881.76	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

NA2 CLK
 24/5/2021 1600
 PIP
 3 DAYS
 AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: