

REPAIR DETAILS

SLU7005 M

TP/CHINA

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Jun 2021)
Parts: M1-SUV HYUNDAI TUCSON 2.0 (A) (Catalogue: Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLU7005M)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 PC REAR BUMPER	0.00	0.00	*220.00 F	✓
2	1		*1 PC REAR BUMPER LOWER SKIRT	0.00	0.00	*270.00 F	✓
3	1		*1 PC REAR BUMPER REINFORCEMENT	0.00	0.00	*145.00 F	✓
4	1		*6 PCS REAR BUMPER CLIPS @2/PC	0.00	0.00	*12.00 F	✓
5	1		*1 PC TAILGATE LOWER PROTECTOR	0.00	0.00	*210.00 F	✓
6	1		*1 PC TAILGATE LOWER PROTECTOR EMBLEM (TUCSON)	0.00	0.00	*35.00 F	✓
7	1		*1 PC TAILGATE LOWER PROTECTOR EMBLEM (TURBO)	0.00	0.00	*35.00 F	✓

F=Franchise part.

Total Parts (S\$) 927.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 SET REVERSE SENSOR	250.00
Sub Total (S\$)			250.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
1	REMOVE & REFIX REAR BUMPER ASSY, LOWER SKIRT, TAILGATE LOWER PROTECTOR & REALIGN THE SAME	New	400.00
2	PUTTY & RESPRAY ON REAR BUMPER, TAILGATE LOWER PROTECTOR	New	400.00
Gross Labour Cost (S\$)			800.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >