

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI21006101/UQCE2

**Date:** 09/06/2021

### REFERENCE

Insured/Claimant: NG YEE KIAT Policy No: DMPCSNW00065402000  
Date of Loss: 17/05/2021 Nature of Claim: OD Claim No: SNM21D202851/C01/TOHHS

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD8935L**  
Make & Model: SUBARU FORESTER, 2.0 XT CVT AWD SR (A) Engine No: FA20A962471  
Reg. Date: 30/06/2016 (Man. Year: 2016) Chassis No: JF1SJGK85GG074391  
Colour: Silver Odometer: 228563 km  
Engine Capacity: 1998 cc  
Market Value/New Car Price: S\$61,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 5 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	100.00	0.00	100.00	100.00
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>100.00</b>	<b>0.00</b>	<b>100.00</b>	<b>100.00</b>
<b>- Excess (S\$)</b>	<b>1,250.00</b>	<b>250.00</b>	<b>1,000.00</b>	<b>80.00</b>
<b>Nett Amount (S\$)</b>	<b>-1,150.00</b>	<b>-250.00</b>	<b>-900.00</b>	<b>78.26</b>

### INSPECTION

Date of Assignment: 24/05/2021 Present Location: Car City Auto Centre Pte Ltd (HQ)  
Date Inspected: 24/05/2021 Inspected At: Car City Auto Centre Pte Ltd (HQ)  
Estimated Period of Repair: 0.0 days Blk 9006 #01-198, Tampines Street 93  
Singapore 528840

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

TOTAL LOSS ASPECT

Market Value :	\$61,000.00
OMV :	\$19,805.00
PARF Rebate (1) :	\$14,853.00
Quota Premium Paid :	\$57,010.00
COE Rebate (2) :	\$29,059.00
Total Rebate (1) + (2) = :	\$43,912.00

The total amount incurred will be Market Value \$61,000.00 minus Total Rebate \$43,912.00 = \$17,088.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jun 2021)
Parts:	M1-SUV	SUBARU FORESTER 2.0 XT CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD8935L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<hr/>				
<b>Miscellaneous Items</b>				
1	1	TOWING	100.00	0.00
			<hr/>	
<b>Sub Total (\$\$)</b>			<b>100.00</b>	<b>0.00</b>
			<hr/>	

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >