



Your Ref : SNM21D202851/C01/TOHHS

Date: 09th June 2021

Our Ref : CS/CTI21006101/Uqce2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLD 8935L
ACCIDENT ON 17/05/2021**

Instruction was received to inspect the vehicle Reg. No. SLD 8935L. The inspection was conducted on 24/05/2021 at the premises of M/s Car City Auto Centre Pte Ltd, Blk 9006 #01-198, Tampines Street 93, Singapore 528840.

The following vehicle information was recorded:

Registration Number	: SLD 8935L
Make/Model	: Subaru Forester 2.0 XT CVT AWD SR
Year of Registration	: 2016
Body Colour	: Silver
Chassis Number	: JF1SJGK85GG074391
Engine Capacity	: 1998 cc

The vehicle sustained damages at the front portion. The undercarriage affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 61,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 43,912.00)
Nett Liability	<u>S\$ 17,088.00</u> =====

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.