



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

China Taiping Insurance (Singapore) Pte Ltd		NAME :		WIP : 44690	
5 Anson Road		ADDRESS :		EXCESS :	
#16-00 Springleaf Tower				DATE: 22-May-21	
Singapore 079909		TEL :			
ATTN : MOTOR CLAIMS					
FAX :					
VEH NO :	SMG8086J	DATE IN :		CONTACT PERSON :	JESS 63310685
CHASSIS NO :	WMWLN720102H57286	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY
MODEL :	MINI Cooper S Clubman RHD	DATE REG.:	31-Dec-18	POLICY NO. :	

NATURE OF WORKS

Parts Description

S/NO	QTY	/UNIT	1ST SUPP	REVISED	PRICES
1	REAR BUMPER <i>scd</i>	1	M51.12.7.422.840	1,190.93	1,190.93
2	GUIDE FOR BUMPER RH <i>? xsu</i>	1	M51.12.7.348.902	76.11	76.11
3	REAR BUMPER LOWER SPOILER <i>? xsu</i>	1	M51.12.7.381.214	290.29	290.29
4	TOWING COVER RH <i>X su</i>	1	M51.12.7.448.138	56.23	56.23
5	LEFT PROTECTION FILM <i>scd</i>	1	M51.12.7.427.273	13.97	13.97
6	RIGHT PROTECTION FILM <i>scd</i>	1	M51.12.7.427.274	13.97	13.97
7	EXPANDING NUT <i>scd</i>	2	B51.12.7.020.321	1.30	2.60
8	EXPANDING RIVET <i>scd</i>	4	M51.11.1.908.077	0.65	2.60
9	CLIPS <i>scd</i>	2	M51.49.7.207.958	5.59	11.18
10	SUPPORT, PDC LH <i>scd</i>	1	M51.77.7.381.965	28.35	28.35
11	SUPPORT, PDC RH <i>scd</i>	1	M51.77.7.381.966	28.34	28.34
12	SENSOR GASKET <i>scd</i>	4	B66.20.9.283.203	6.70	26.80
13	REAR BUMPER LIGHT RH <i>scd</i>	1	M63.21.7.352.158	192.53	192.53
14	EXHAUST PIPE CHROME RH <i>repair</i>	1	M18.30.8.654.203	143.97	143.97
TOTAL PARTS					1511.27
TOTAL PARTS COST					2,077.87

SUPPLEMENTARY

NO	DESCRIPTION	QTY	PARTS NO	/UNIT	1st Supp	REVISED	PRICES
1	REPLACE REAR BUMPER. REPAIR AREAS AFFECTED BY THE ACCIDENT.					840	1,260.00
2	TO RESPRAY REAR BUMPER.					800	1,000.00
3	TO TRANSFER THE REVERSE SENSORS.					150	300.00

TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT 150 ✓	250.00
5 TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT 250 ✓	350.00
6 SUNDRIES.	NETT 120 ✓	50.00
TOTAL LABOUR		2210 - 3,210.00
TOTAL PARTS		- 2,077.87
TOTAL		- 5,287.87
LESS EXCESS		- -
TOTAL AFTER EXCESS		- -
GST 7%		- -
GRAND TOTAL		- -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resu
Hp 90010068
3 days
25/05/21 @ 1500
Res before paint

151127
2210100
3721127