

NO STOCK
NO \$
S8 Co: Appd 1130A
LKK Kamoh

CO. REG. NO: 199402370D
GST NO: M2-0123250-3

W. Kim Hin AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 31817

Vehicle Insured : SME 4066 D
Accident Date : 13-May-2021

Date : 18-May-2021

Our Ref : 021194 (CHINA) / QUEK

PAGE : 1

HO YENG FANG (MR)
Singapore

A200A-0013073

Not Authorized

Phenny B4Paim

82494.45

4 days

ESTIMATED COST OF REPAIR FOR TOYOTA RAIZE 1.0 XS CVT (2021) SMX7506G

1 pc	rear bumper	CM	630	✓	
1 pc	rear bumper lower	nuha	664	✓	
8 pcs	rear bumper lower clips(white)	nu	76.80	✓	
1 pc	o/s rear bumper outer garnish	nu	88.00	✓	
1 pc	o/s rear bumper parking sensor	CM	576.00	✓	415.00
1 pc	o/s rear bumper side retainer	nu x	56.00	x	
12 pcs	rear bumper clips	nu	46.80	✓	
1 pc	rear end panel	n ?	400.00	x	
1 pc	rear end panel inner air grille	n ?	99.00	✓	
1 pc	o/s rear fender inner shield	nu x	120.00	x	
4 pcs	o/s rear fender inner shield clips	nu x	15.60	x	
1 pc	o/s rear fender wheel arch garnish	? nuha	110.00	✓	
	rear bumper parking sensor cover	CM	63.00	✓	
					0.00
			Less 25% :		0.00
					0.00

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

400l
600.00

To remove and refit reverse sensor assy.

60.00 50l

To putty and respray on affected portions.

600.00 400l

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : SME 4066 D
Our Ref : 021194

Page : 2
No. : 31817

To apply undersealing

~~ 60.00 X

Total : S\$ 1,320.00
=====

Singapore Dollars One Thousand Three Hundred
and Twenty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.