



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

08 JUL 2021

Your Ref : SNM21D202482/C02/SKP7288B/TOHHS
Our Ref : TP/11732/FBM5095B/SKP7288B

BY EMAIL

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

ATTN: Mr. Alfred Toh

Dear Alfred,

Accident involving FBM5095B & SKP7288B on 28/04/2021

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

1. Cost of Repair (Inc 7% GST)	\$5,457.00
2. Loss of Use (4 days x \$20)	\$ 80.00
3. GIA Vehicle Insurance Search Fee	\$ 2.00
TOTAL	<u>\$5,539.00</u>

We attached our Tax Invoice and GIA Search Invoice for your perusal.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext. 220.

Thank you.

BAN HOCK HIN CO PTE LTD

Raymond Tan
Manager/Insurance Dept

