

**REPAIR ESTIMATE\***

VEHICLE NO SHD4541M

DATE 18.05.21

MAKE :

MODEL : HYUNDAI IONIQ

CHIANG/CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT DOOR OUTER HANDLE LH			Ry \$234.80
1	REAR FUEL TANK LID			Ry \$83.30
	<b>SUB TOTAL</b>			<b>\$318.10</b>
	<b>LESS 20%</b>			<b>\$63.62</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$254.48</b>
1	FRONT DOOR ADVERTISEMENT LH			cut \$100.00
1	REAR FENDER ADVERTISEMENT LH			cut \$100.00
1	PETROL STICKER			new \$20.00
1	FRONT DOOR COMFORT LOGO STICKER			new \$75.00
1	REAR DOOR COMFORT APP STICKER			AN x \$80.00
			295	<b>\$375.00</b>
	<b>Labour Charge</b>			
	Panel Beating			350 \$600.00
	Spray Painting Charge			500 \$600.00
	Remove/refix door parts			nn x \$120.00
	Check Wiring			nn x \$60.00
	<b>TOTAL LABOUR</b>		850	<b>\$1,380.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$2,009.48</b>
			\$1145	
			* 3 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495749  
 WP 19/5/21 @ 2pm  
 Resurvey after repair.  
 Tanpin @ khands.com  
 2-3 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: