

(08/11/13) Wef
ASS. REC. BY: Marcus

REF:

CC3/MSG21006112/49f3

ASSIGNMENT

From:
Estimated Cost:

Date:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn:

C.C

A/C:

T/Radio: Insured / Std / NI / NA

Rear

R/Bal.

L/Bal.

D.O.I.

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

Date/Time, File Pass to?

☐

: Preli. Report

18/06/20 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

MER-TP

Lump Sum ~~11.5k~~ (\$ 5000)

Submit to insurance

Not Authorized
Lkh
24/5/21
1/5 \$5000
7 days

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6 #01-48
SINGAPORE 417883

VEHICLE No: SLK 2045H

1PC	BOOTLID	Bodyltd	522.50	\$841.20
1PC	BOOTLID INNER LOCK	Butl/twi	105.70	\$195.30
1PC	BOOTLID LOCK STRIKER	u1		\$50.80 X
1PC	BOOTLID 'H' LOGO	rec	32.50	\$45.00
1PC	BOOTLID 'I-VTEC' EMBLEM	rec	41.00	\$52.00
1PC	BOOTLID 'CITY' EMBLEM	rec	40.00	\$50.00
1PC	BOOTLID OUTER CHROME HANDLE	one	72.90	\$325.00
1PC	BOOTLID INNER TRIM	11		\$244.20 X
2PCS	BOOTLID REFLECTORS @\$288.50	N/S one	85.50	\$577.00 1PC
1PC	BOOTLID WEATHERSTRIP	twi	84.70	\$215.00
1PC	REAR BUMPER	Dis	463.70	\$642.20
2PCS	REAR BUMPER SIDE RETAINERS @\$35.00	N/S But	25.00	\$70.00 1PC
2PCS	REAR BUMPER REFLECTORS @\$65.00	11		\$130.00 X
1SET	REAR BUMPER CLIPS	rec	39.00	\$45.00
1PC	REAR END PANEL	Bodyltd	380.80	\$605.00
1PC	REAR END PANEL TOP GARNISH	twi	80.50	\$199.50
2PCS	TAILLAMPS @\$425.00	N/S one	205.70	\$850.00 1PC
2PCS	TAILLAMP HOUSING PANELS @\$305.00	N/S But	165.20	\$610.00 1PC
1PC	REAR FLOOR PANEL	R		\$911.40 X
1PC	REAR FLOOR PANEL TOP BOARD	Torn	51.40	\$422.80
2PCS	REAR FENDERS \$1588.00	N/S Buc	015R 1334.00	\$3,176.00 1PC
2PCS	REAR FENDER INNER TRIMS @\$299.00	11		\$598.00 X
1PC	REAR EXHAUST	11		\$588.20 X
1PC	REAR EXHAUST HEATSHIELD	11		\$45.00 X
1PC	REAR LOCK ANTENNA SENSOR	11		\$233.20 X
				\$11,721.80

(207

1SET	REAR BUMPER REVERSE SENSOR	sketch	\$280.00 200
1PC	REAR END PANEL SEALANT	rec	\$50.00 ✓
1SET	REAR FLOOR PANEL INSULATOR	11	\$200.00 X
1SET	BOOTLID INNER TRIM CLIPS	11	\$50.00 X
1PC	REAR WINDSCREEN SEALANT	rec	\$50.00 40
1PC	REAR WINDSCREEN INNER SEAL	rec	\$50.00 30

TO CHECK WIRING	\$80.00 30
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00 50
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00 80
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00 X
TO DISMANTLE FUEL TANK	\$100.00 60
TO TRANSFER BOOTLID MECHANISM	\$100.00 60
TO SPRAY RUST PROOFING	\$120.00 100
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,800.00 1400

TO PUTTY & SPRAY PAINTING

\$1,500.00 1180
\$14,524.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9-3732.60
207/
9-2984.48
S.N. 320.00
L-2960.00