

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0441/2021/TF  
DATE : 24-May-21  
WIP : 28384

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/5/21

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

OWNER'S NAME : MR. PHOON YEE WEI  
ADDRESS : 114F FIDELIO ST  
SINGAPORE 458488  
  
TELEPHONE : HP +65 9066 1311  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 2100452593-05  
VEHICLE NO : **SLA 479 E**  
MODEL CODE : A4 SEDAN 1.4 TFSI S tronic  
MODEL YEAR : 19/2/2016  
ENGINE NO : CVN 002314  
CHASSIS NO : WAUZZZF46GA021643  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 24-May-21  
PLACE OF ACCIDENT : JUNCTION OF FIRST ST AND SECOND ST

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLA 479 E**

| S/N                         | NATURE OF JOBS                                                                                                                                | ESTIMATED CHARGES           | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|----------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.                 | S/N \$ 360.00               | x ✓                        |
| 2                           | TO REMOVE AND TRANSFER RHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.                                                                        | S/N \$ <del>350.00</del>    | 250 ✓                      |
| 3                           | TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ <del>2,100.00</del>      | 1000 ✓                     |
| 4                           | TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET.                                                                                         | \$ <del>3,000.00</del>      | 1100 ✓                     |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                | S/N \$ 192.00               | ✓ ✓                        |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                               | <b>: \$ <u>6,002.00</u></b> |                            |

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 479 E**

|                              |                                                        |     | DAMAGED PARTS & PRICES |           |
|------------------------------|--------------------------------------------------------|-----|------------------------|-----------|
| S/N                          | PARTS DESCRIPTION                                      | QTY | S/NETT                 | REMARKS   |
| 1                            | FRONT BUMPER <i>Dehnd</i>                              | 1   | \$ 2,111.00            | ✓ 1688.80 |
| 2                            | FRONT BUMPER FIXING PARTS <i>men</i>                   | 1   | TBC                    | +         |
| 3                            | FRONT BUMPER SECURING STRIP <i>Dang d</i>              | 2   | \$ 71.00               | ✓ 56.32   |
| 4                            | FRONT BUMPER CENTER GRILLE - CENTER <i>men</i>         | 1   | \$ 196.00              | +         |
| 5                            | FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>men</i> | 1   | \$ 210.00              | +         |
| 6                            | FRONT BUMPER AIR GUIDE - RH <i>men</i>                 | 1   | \$ 63.00               | +         |
| 7                            | FRONT BUMPER AIR GUIDE GRILLE - RH <i>men</i>          | 1   | \$ 365.00              | +         |
| 8                            | RADIATOR GRILLE <i>crushed</i>                         | 1   | \$ 1,819.00            | ✓ 1455.20 |
| 9                            | FRONT BUMPER FOAM FILLER PIECE ? nn                    | 1   | \$ 124.00              | ? X       |
| 10                           | FRONT BUMPER REINFORCEMENT ? nn                        | 1   | \$ 845.00              | ? X       |
| 11                           | FRONT BUMPER TOP COVER <i>men</i>                      | 1   | \$ 127.00              | +         |
| 12                           | FRONT BUMPER GUIDE SECTION - RH <i>Dang d</i>          | 1   | \$ 38.00               | ✓ 29.84   |
| 13                           | CAUTION STICKER <i>men</i>                             | 1   | \$ 14.00               | +         |
| 14                           | A/C STICKER <i>men</i>                                 | 1   | \$ 8.00                | +         |
| 15                           | FRONT LOCK CARRIER BRACKET <i>men</i>                  | 1   | \$ 137.00              | x.        |
| 16                           | FRONT BUMPER SUPPORT - LH / RH ? nn                    | 1   | \$ 58.00               | ? X       |
| 17                           | HORN - RH ? nn                                         | 1   | \$ 126.00              | ? X       |
| 18                           | HORN BRACKET - RH ? nn                                 | 1   | \$ 29.00               | ? X       |
| 19                           | FRONT FENDER - RH <i>Distorted</i>                     | 1   | \$ 767.00              | ✓ 613.20  |
| 20                           | FRONT FENDER ATTACHMENT PARTS <i>men</i>               | 1   | \$ 202.00              | +         |
| <b>SUB TOTAL SPARE PARTS</b> |                                                        | :   | <b>\$ 7,310.00</b>     |           |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 479 E**

|                      |                                                            |     | DAMAGED PARTS & PRICES |           |
|----------------------|------------------------------------------------------------|-----|------------------------|-----------|
| S/N                  | PARTS DESCRIPTION                                          | QTY | S/NETT                 | REMARKS   |
| 21                   | FRONT FENDER CLOSING ELEMENT - RH <i>Distorted</i>         | 1   | \$ 72.00               | ✓ 57.52   |
| 22                   | FRONT FENDER BRACKET - RH ? <i>distorted</i>               | 1   | \$ 35.00               | ? 27.92   |
| 23                   | FRONT FENDER DEFORMATION BRACKET - RH <i>new</i>           | 1   | \$ 49.00               | +         |
| 24                   | FRONT FENDER RIVET <i>new</i>                              | 7   | \$ 24.00               | ✓ 18.48   |
| 25                   | FRONT FENDER BRACE - RH ? <i>bent</i>                      | 1   | \$ 118.00              | ? 94.40   |
| 26                   | FRONT FENDER TOP COVER ? <i>deformed</i>                   | 2   | \$ 54.00               | ? 42.56   |
| 27                   | FRONT WHEEL HOUSING LINER - RH <i>Deformed</i>             | 1   | \$ 241.00              | ✓ 192.80  |
| 28                   | FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - RH <i>new</i> | 1   | TBC                    | +         |
| 29                   | FRONT WHEEL SPOILER - RH <i>new</i>                        | 1   | \$ 73.00               | +         |
| 30                   | STONE CHIP[ GUARD <i>new</i>                               | 1   | \$ 51.00               | +         |
| 31                   | FRONT HEADLIGHT - RH <i>cracked</i>                        | 1   | \$ 7,693.00            | ✓ 6154.40 |
| 32                   | FRONT HEADLIGHT POWER MODULE - RH ? <i>new</i>             | 1   | \$ 761.00              | +         |
| 33                   | FRONT HEADLIGHT CONTROL UNIT - RH                          | 1   | \$ 751.00              | +         |
| 34                   | FRONT HEADLIGHT HOSE - RH <i>new</i>                       | 1   | \$ 36.00               | +         |
| 35                   | FRONT LIFT CYLINDER - RH ? <i>cracked</i>                  | 1   | \$ 210.00              | ? 167.60  |
| 36                   | FRONT LIFT CYLINDER BRACKET - RH ? <i>nec</i>              | 1   | \$ 6.00                | ? 4.80    |
| 37                   | FRONT LIFT CYLINDER HOSE <i>new</i>                        | 1   | \$ 93.00               | +         |
| 38                   | FRONT RADIATOR AIR GUIDE <i>new</i>                        | 4   | \$ 78.00               | +         |
| 39                   | FRONT NO. PLATE <i>new</i>                                 | S/N | \$ 60.00               | ✓ 60.00   |
| 40                   | SUNDRIES ? <i>nec</i>                                      |     | \$ 350.00              | ? 21.76   |
| TOTAL SPARE PARTS    |                                                            | :   | \$ 18,065.00           |           |
| TOTAL LABOUR CHARGES |                                                            | :   | \$ 6,002.00            |           |
| GRAND TOTAL          |                                                            | :   | \$ 24,067.00           |           |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian Lij  
24/05/21.

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 04 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT